

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sections 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records, Volume 9 Page 3743)

Set ¼ sec. post, from which
 A Fir 36" dia. bears N.16°E., 40 lks. dist.
 A Fir 12" dia. bears S.11°W., 33 lks. dist.

A. Boyer, For: Harry Bryson, March 1943 - C.S. File 36/58

Orig. 42" Fir BT, N.16°E., 26.4 ft.
1" Bar.
New tree, 20" Maple, S.15°W., 31.7 ft.

Doug. Co. Surveyors Off. James Byron; G. Welker; J. Fee
November, 1956 - C.S. File 47/133

Found - Orig. NE BT, bark scribed ¼ S12, top scribing 5 ft.
 above ground, has yellow tag set by Haines in
 1943. Also tag set by BLM 1956. BT is now 42".
 NE BT alive and good condition.

 The SW BT is gone. Would be in roadway. Corner
 checks call to creek.

Set brass cap at cor. mkd: County Surveyors Office, 1956

¼S 12 T25S R4W

13 . Set cap 1" below surface. From which:
 14" hemlock bears S.17°W., 53.0 ft. scribed ¼ S13 CSBT.
 10" Maple S.17°W., 33.0 ft. scribed ¼ S13 CSBT, 20 yrs ±
 down.

Bureau of Land Management Dependent Resurvey - Corbin, Zirpel
and Roseberry - Special Instructions dated July 8, 1957 and
July 15, 1958 - (DCSO records, Volume 29 Page 12276)

Found - 1956 DCSO brass cap/iron pipe.
 40" Fir bears N.16°E., 40 lks dist. bark scribed
 ¼ S12 BT over a healed blaze. (Orig.)
 Fir 18" dia. bears S.17°W., 81½ lks. dist. with
 scribe marks ¼ S13 CS BT visible on open blaze.
 (1956 BT)

(Continued Next Page)

TOWNSHIP 25 RANGE 04 POINT IDENTIFIER # 640500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 12 and 13

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

At the corner point, set an iron post, 28" long, 2½" dia., 6"
below the surface of the road, with brass cap mkd: T25S R4W
¼ S 12
S 13
1957

from which

A Fir 40" dia. bears N.71°E., 100 lks. dist. marked
¼ S12 BT.

A Cedar 17" dia. bears S.73½°W., 98 lks. dist. marked
¼ S13 BT.

Reset the iron pipe alongside the iron post.

The corner falls in a graveled and maintained road, 25 lks
wide, bears N.55°E. curving to N. and S.55°W., curving to W.

Fd. Ok by Kris DeGroot - March 2003 - M137-57

Found OK by K. DeGroot, May 2004 - M146-4

FD. ok by Kris DeGroot, 8/2008 - 2008-0061A-G