

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION Township Cor. - SW Cor. Sec. 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

No suitable trees available in secs. 1 and 36 within limits.
Found OK, Donald Bentz - Sept. 1986 - M 102-48 & M 106-4 Fd. OK, M. Smalley, July 1995 - M 119-67
Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/11/98 - C.S. File 64/79-26 ----- Found - 3½" dia., brass cap on a 2½" O.D. iron pipe, protrudes 5" above ground. 1963 BLM 10" now 41" dia., D.Fir with fully healed blazes, bears N.18½°E., 146.0 ft. (1955 rec. N.17°E., 146.0 ft.) 1955 DCSO 16" now 30" dia., triple trunked down D.Fir with a fully healed blaze root hole near. (Rec. S.84°E., 600.0 ft) 1955 DCSO New BTs- 30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.13°W., 427.0 ft. 30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.60°E., 324.0 ft. Note - Corner lies at the intersection of fences running East, West, & North. No trees south of line. See sketch in file.
DCSO-GIS Corner visitation - 7/7/2004 - Typed: 01/25/2011 - C.S. File 67/33-1 ----- Monument - BC/IP 1.25" Comment - ok
Fd. BC by M. Schulze, 11/2012 - M164-47