

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 24, T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T25S
R6W R5W
¼
S 24|S 19
1999
PLS 1941

2 3/8" DCSO brass cap on a 1 3/8" O.D. iron pipe protrudes 8" above ground, 1997, bears N.15°W., 35.06 ft., from alum. cap/IR.

Bearings & dist. taken from 1999 alum cap/IR

14" now 25" dia., D.Fir with a fully healed single blaze bears N.25¼°E., 54.1 ft., (Note blaze faces S.65°W.) 1972

6" now 21" dia., D.Fir with a fully healed single blaze N.87½°W., 12.6 ft. (Note blaze faces North) 1972

7" now 7" dia., Ash with an unhealed double blaze scribing visible "¼ S24 CS BT", bears N.14½°W., 44.6 ft. 1997

Removed- 1997 DCSO brass cap is sawn off, iron pipe and a yellow plastic cap set in center, iron pipe protrudes 6" above ground.

Note - Corner lies 10 ft. west of centerline of drive way. This renewal reflects recent survey by PLS 1941 (Kris DeGroot, BTS) that determined corner position based on old subdivision ties.

Fd. by ODOT 1/7/2009 - C.S. File 65/66-2

2