

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 100640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & Sec. 1, T25-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, contract #31 dated April, 1853  
-----  
Set ¼ sec. post, from which  
    A Y.Oak 18" dia. bears N.22½°W., 44 lks.  
    A Y.Oak 14" dia. bears N.60°E., 12 lks.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey; Clete Putnam - May 4, 1960 - C.S. File 49/124-63  
-----  
Found - Both orig. BTs. Orig. 18" now 30" B.O. N.22½°W., 29.0 ft. I opened & find good scribing "S".  
    Orig. 14" now 25" B.O. N.60°E., 8.0 ft. shows old scars.  
Set brass cap at cor. mkd. County Surveyor's Office, 1960  
                                    ¼ S 1 | S 6 T25S  
  R6W F5W  
New BT - 10" B.Oak bears N.74°W., 42.8 ft. scribed ¼ S1 CSBT  
          17" B.O. bears S.41°E., 20.2 ft. scribed ¼ S6 CSBT.  
(Sketch in CS File of relationship of cor. & fences)

Found OK, Aug. 8, 1963, M.E.G. C.S. File 49/123-106

Douglas County Surveyors Office - Randall Smith & Stephen Flause - May 20, 1997 - C.S. 64/74-36  
-----  
Found - 2½" dia Brass cap on a 1½" O.D. iron pipe, protrudes 14" above ground.  
    18" now 30" dia. down and rotted oak, scribing found "¼" root hole agrees with rec. "N.22¼°W., 29'" OBT.  
    Orig. NE BT now gone  
    10" now 16" dia. B.Oak, with a fully healed double blaze, bears N.74°W., 42.8' (agrees with rec.) 1968.  
    1960 SE BT now gone.  
New - 24" dia. W.Oak, with an open hole near base is single blazed and scribed "¼ S6 CS BT", bears S.75½°E., 41.9'.  
    11" dia. D.Fir, double blazed and scribed "¼ S1 CS BT", bears N.63½°W., 15.5'.  
    5" dia. W.Oak, double blazed and scribed "¼ S1 CS BT", bears N.23°W., 14.2'.  
Corner lies 1' south of a 3 way fence corner w/ fences running E-W and N.

Found OK by C. Sweeden, Sept. 2000 - M135-57  
Fd. Ok by C. Sweeden, 4/2008 - 2008-0064