

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set ¼ Sec. post, from which  
A Y.oak 30" dia. bears S.47°W., 38 lks. dist.  
A Fir 36" dia. bears N.29°E., 21 lks. dist.

F.C. Frear, Deputy Co. Surveyor - Wit. R.L. Stearns; Bob Davis  
Feb. March 1919 - R.M. 1-4, C.S. File 2/17; F.B. 46 Pg. 14  
For: Stearns Estates  
-----

Renew from old BTs. Set a 2" x 40" Iron Pipe and a 4" x 40"  
Cedar stake, from which:  
A 40" Bull Pine bears S.75½°E., 86 lks.  
A 40" Fir bears N.29°E., 21 lks.  
A 36" B.Oak bears S.47°W., 38 lks.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey; Clete  
Putnam - May 4, 1960 - C.S. File 49/124-53  
-----

Found - 1½" Iron Pipe at corner & now 44" Fir N.29°E., 13.9  
ft. measured from face, shows good scar, I do  
not open.  
S.E. BT gone.  
36" B.Oak stump, rotted S.45°W., 25.1 ft.  
New BTs - Rescribe, now 44" Fir N.29°E., 15.9 ft. (bark  
scribe) ¼ S8 CS BT.  
11" R.Fir S.82°W., 44.3 ft. scribed ¼ S7 CS BT.  
Fence cor. bears approx. N.20°E., 25 ft.

Fd. Ok. - Larry Dolan - July 1993 - M 117-41

Douglas County Surveyors Office - Randall Smith & Stephen  
Flause - June 23, 1997 - C.S. 64/75-11  
-----

Mon. FD.- 1½" O.D. iron pipe protrudes 6" above ground leans  
westerly 6" from plumb. (1919)  
Bt's Fd.- 36" now 46" dia. 4' high tipped out of ground D.Fir  
stump, with a previously opened healed blaze  
and bark scribing and "S8" visible, large root  
hole near record bearing "N.29°E., 13.9'" OBT.

(Cont. Next Page)

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Orig. SW BT not found  
SE BT from 1919 renewal not found  
11" now 24" dia. 1' high D.Fir stump, with a fully  
healed lower blaze, bears S.82°W., 44.3'. 1960  
Mon. Set- 2 3/8" dia. brass cap on a 1 3/8" O.D. by 32" long  
iron pipe is set at plumb position of found  
iron pipe, protrudes 6" above ground. Found  
I.P. measures 33 1/2" long is set along north  
edge of BC/IP protrudes 4" above ground.

DOUGLAS COUNTY SURVEYORS OFFICE

T25S R5W

1/4  
S7|S8  
1997

New Accessories -

- 7" W.Oak, double blazed and scribed "1/4 S7 CS BT",  
bears N.27 1/2°W., 33'.
- 5" I.Cedar, double blazed and scribed "1/4 S7 CS BT",  
bears N.48°W., 13.5'.
- 4" I.Cedar, double blazed and scribed "1/4 S8 CS BT",  
bears S.54°E., 11.4'.
- 6" Madrone, double blazed and scribed "1/4 S8 CS BT",  
bears N.71°E., 15.5' to base of scribed trunk.
- 8" Nail through a 2" dia. Washer and BT tag is set  
in top of 24" dia. D.Fir stump from 1960  
renewal (S82°W., 44.3').

Corner lies at the NE corner of a clear cut. Corner lies 7'  
west of a down N-S running fence line.

Fd. by ODOT 1/7/2009 - C.S. File 65/66-1