

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Elder & Gile, Contract #31 dated April, 1853 ----- Set ¼ Sec. post, from which A Y.Oak 16" dia. bears N.47½°E., 26 lks. A Y.oak 10" dia. bears N.57½°W., 60 lks.</p>
<p>F.C. Frear, Deputy Co. Surveyor - Wit. R.L. Stearns. Bob Davis - March 1919 - For: Stearns Estates - R.M. 1-4 C.S. file 2/17 and F.B. 46 Pg. 26 ----- Renew from old BT. Set a 1" x 40" Iron pipe and a 4" x 36" Cedar stake, from which A 24" Fir bears N.26°W., 8 lks. A 36" Madrone bears S.72¾°W., 45 lks.</p>
<p>James W. Byron, Deputy - Milo E. Godfrey; Clete Putnam April 20, 1960 - C.S. File 49/124-50 ----- Found - Frear's BTs, now stumps & Iron pipe at corner. Set - Brass cap at cor. & alongside I.P. Mkd. BC County Surveyors Office 1960, ¼ S8 S9 T25S R5W. New - 13" W.Oak bears N.72°W., (71.0 ft. L.L.) scribed ¼ S 8 CS BT. 34" B.Oak bears S.8°E., 76.0 ft. scribed ¼ S9 CSBT.</p>
<p>DCSO 1960 Brass cap found in 1962 by BLM - Patrick Reynolds Group # 476 - DCSO records Volume 31 Pages 13152-53.</p>
<p>Found I.P., L. Dolan, Feb. 1987, M 103-56</p>
<p>Douglas Co. Surveyors Office - Randall Smith; Stephen Flause June 29, 1988 - C.S. File 62/52-5 ----- Found - 1" O.D. Iron pipe flush with ground. Top was broken off. A small 4" section of 1" I.P. found near corner. (Probably 1" I.P. from Frear) DCSO BC/IP not found. All original BTs gone. 24" now 30" dia. 6 ft. high D.Fir stump with a burnt out blaze, no scribing visible, bears N.26°W., 6.0 ft. (Rec. 5.3 ft. is a face measurement) 36" now 36" dia. 3 ft. high Madrone stump in a cluster of small Madrones, stump has a rotted out blaze, no scribing visible, bears S.72¾°W., 29.7 ft. (agrees w/rec)</p> <p>continued next page</p>

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

	13" now 18" dia. W.Oak with a fully healed single blaze, bears N.74°W., 70.6 ft. (agrees w/1964 BLM resurvey)
	34" now 34" dia. down 7 rotting Oak with visible scribing "11" bears S.8°E., 76.0 ft. (agrees w/ record) Byron, 1960.
Set -	Position of 1" O.D. I.P. referenced and a DCS0 BC/IP measuring 1¼" O.D. x 32" long, set in referenced position. Found 1" I.P. dug out to 30" & broke off, remaining I.P. immovable & left in ground. 1" x 30" long piece of I.P. reset along North side of DCS0 BC/IP protruding 4" above ground. BC/IP protrudes 5" above ground
New BTs-	7" Maple double blazed & scribed ¼ S9 CS BT bears N.61°E., 43.3 ft.
	18" D.Fir double blazed & scribed ¼ S9 CS BT bears S.57°E., 34.3 ft.

Found OK by D. Edwards, Mar. 1998 - M 128-46