

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 & 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Elder & Gile, Contract #31 dated April, 1853 ----- Set - ¼ Sec. post, from which A W.Oak 11" dia. bears N.42½°W., 35 lks. dist. A Y.Oak 22" dia. bears S.61½°E., 67 lks. dist.</p>
<p>Ben B. Irving, Deputy - Alfred Hand; R.L. Irving - May 1, 1928 - C.S. File 14/30 ----- Drove a Ford axle for corner in position of old stub placed by B.H. Manning in position of original corner. A 14" Cedar bears S.70°E., 92 lks. An 8" B.Oak bears S.12°W., 57 lks. Affidavits in C.S. File 14/30 by H.L. Kruse, B.H. Manning and Alfred Hand, witnesses - who state that this is the proper location of the corner.</p>
<p>Douglas Co. Surveyors Office - Gary Langlitz; Clell Goodwin; A.V. Cangie; M.Lenora Ladig - July 1, 1975 - C.S. 57/34-1 ----- Found - An axle set flush in the ground approx. 1 ft. south of a fence corner of fences running North, South and East., From which: A 14" now 32" I.Cedar bears S.70°E., 60.7 ft. A 8" now 20" B.Oak bears S.12°W., 37.6 ft. We find no original evidence. This corner lies approx. 50 ft. East of a farm house.</p>
<p>Fd. Axle, R. Dolan, Sept. 1992, M 115-75</p>
<p>Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - Oct. 14, 1997 - C.S. 64/78-13 ----- Found - 1" axle shaft protrudes 1" above ground. (1928) 14" now 35" dia Cedar, with a fully healed single blaze, bears S.62½°E., 60.7' (rec. S.70°E., 60.7') 1928. 9" now 25" dia. B.Oak, with a fully healed blaze, bears S.18°W., 36.6' (rec. S.12°W., 37.6') 1928. New - SE Corner of concrete garage foundation, bears S.37½°W, 60'. SE Corner of concrete house foundation, bears S.85°W., 52.7'. Corner lies 1' south and 1½' west of a fence corner with fence running N-S and east near top of a knob approx.</p>
<p>Found OK by D. Edwards, July 2000 - 2000-0053</p>