

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 360520

PRIMARY CORNER DESCRIPTION S.E. 1/16 Cor, Section 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Subdivision of Section 9, Patrick Reynolds, Group #476
July-August 1962 - (DCSO Records, Vol. 31 Page 13157)

Set an iron post 30" long 2½" dia. 28" in the ground, with
brass cap mkd. SE 1/16 S9 1962, from which
 A Fir 13" dia. bears S.89°E., 60 lks. dist. mkd.
 SE 1/16 S9 BT.
 A Fir 13" dia. bears S.83°W., 27½ lks. dist. marked
 SE 1/16 S9 BT.

Doug. Co. Surveyors Office - Vernon Tracy & crew
Feb.9, 1967 - C.S. File 49/124-95

Found - 1962 Cadastral I.P. & brass cap pushed over & buried
 good condition.
 13" D.Fir, now snag S.89°E., 39.6 ft. shows "SE 1/16
 S9 BT" scribe on unhealed blaze.
 SW BT pushed over & out of position, scribes
 visible.
Reset brass cap in proper place & mark new BTs:
 11" D.Fir N.19°E., 49.2 ft. mkd. SE 1/16 S9 CS BT.
 11" D.Fir S.5°W., 47.6 ft. mkd. SE 1/16 S9 CS BT.
Corner lies in logged off unit on E. side of rolling spur
ridge, course S.