

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ Sec. post, from which
 A W.Oak 12" dia. bears S.22°E., 17 lks. dist.
 A W.Oak 16" dia. bears N.40°W., 21 lks. dist.

May & Arthur Thiel, July 2, 1900 - Volume 2 Pg 262

Set a stone 20"x15"x5" for cor. from which
 A W.Oak 24" dia. bears S.42½°E., 152 lks. dist.
 A Fir 20" dia. bears S.85°W., 119 lks. dist.
The old BTs have been cut down years ago but one stump re-
maining by which I establish the new cor.

James W. Byron, Deputy; Milo E. Godfrey; Clete Putnam
April 20, 1960 - C.S. File 49/124-51

Found - Both of Thiel's BTs,
 24" now 30" W.Oak S.42½°E., 100.3 ft. shows old
 face, center rotted.
 20" now 30" Fir stump S.85°W., 78.5 ft. I open and
 find good scribing "BT".
 Corner stone Not Found.
Set - Brass cap at cor. mkd. County Surveyors Office 1960
 ¼ S10|S11 T25S R5W
New BTs - 14" R.Fir bears N.61½°W., 27.7 ft. scribed ¼ S10
 CS BT.
 15" R.Fir bears N.84°E., 18.6 ft. scribed ¼ S11 CSBT
Corner is 10 ft. South of E-W fence.

Found OK, 3/77, Victor McLind - M 63-32

Douglas Co. Surveyors Office - R.B. Kimberling; M.W. Cline
September 26, 1977 - C.S. 59/40-24

Found - 1" I.P. with brass cap 1.2 ft. above corner,
 properly mkd. Corner is almost washed out in
 badly eroded East-West trail.
 24" now 30" W.Oak bears S.42½°E., 100.3 ft. with
 rotted out blaze. (Cont. Next Page)

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Found - 20" now 30" Fir stump bears S.85°W., 78.5 ft. with opened blaze & fragmentary scribing. (Theil)
14" Fir stump bears N.61½°W., 27.7 ft. with a well healed blaze.
15" Fir snag bears N.84°E., 18.6 ft. with a well healed blaze.
Set - RESET brass cap 2.0 ft. below orig. ground, re-channeled ditch around brass cap. Stamped B.C. to read "RESET 1977".
New BT - 14" W.Oak bears N.88°E., 49.7 ft. double blazed & scribed "¼ S11 CS BT". Tree is at fence corner West and North.
Corner is 10 ft. South of E-W fence.

Doug. County Surveyors Office - Larry E. Monrean, Deputy John Pike - Oct. 26, 1992 - C.S. File 64/32-11

Found - Iron pipe and brass cap monument 1/2 foot below surface.
Fir stump 19" (Rec. 14") bears N.61½°W., 27.7 ft. Well healed blaze.
14" now 20" W.Oak with partially healed scar bears N.88°E., 49.3 ft.
No other BTs found.
New BTs - 6" Fir double blazed, scribed "X CS BT" bears N.35½°E., 34.5 ft.
6 Fir double blazed, scribed "¼ S10 CS BT" bears N.51½°W., 6.5 ft.
12" Fir double blazed, scribed "¼ S11 CS BT" bears S.88°E., 40.0 ft.

Fd Brass cap, Robert Dolan, LS 1076 - For: Gordon Atterbury - April 1994 - M 120-18

DCSO-GIS Corner visitation - 8/5/2004 - Typed: 1/24/2011 - C.S. File 67/33-1

Monument - 1.25" BC/IP
Comment - OK