

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, Deputy Surveyor, Contract #152
dated June, 1871

Set $\frac{1}{4}$ Sec. post, from which
A Maple, 12" dia. bears S.69°W., 15 lks. dist.
A Maple, 8" dia. bears N.60°W., 19 lks. dist.

G. Robert Lecklider, For: Bernard Grubbe, Sept. 1961
Map File M 21-29

Set by proportionate measurement.
Set $\frac{3}{4}$ " Bolt, from which
22" Fir S.27°E., 80.5 ft.
10" Fir S.30°W., 62.8 ft.

Milo E. Godfrey, Deputy - Michael Stone; Sept. 21, 1962
C.S. File 49/124-79

Found - Both trees mkd. by Lecklider, 1961:
22" Fir S.27°E., 80.5 ft. scribing plainly visible.
Tree in good condition.
10" Fir S.30°W., 62.8 ft. scribing plainly visible,
Tree alive but badly damaged by fire.
 $\frac{3}{4}$ " Bolt set by Lecklider gone, in fire trail.
Set brass cap at cor. mkd. County Surveyors T25S R5W $\frac{1}{4}$ S26
Office 1962 S35
New BT - 36" D.Fir N.76°E., 98.2 ft. mkd. $\frac{1}{4}$ S26 CS BT.

BLM Dependent Resurvey - C. Albert White; Donald Beck
May 3-24, 1963 (DCSO records Volume 32 Page 13366)

Found 1962 brass cap, and found:
A Fir 22" dia. bears S.29 $\frac{1}{2}$ °E., 122 lks. dist. mkd. $\frac{1}{4}$
S35 BT, on double blaze.
A Fir, 10" dia. bears S.30°W., 94 lks. mkd. $\frac{1}{4}$ S35 BT,
on double blaze.
New BT - A sawed Fir stump 24" dia. bears N.63 $\frac{3}{4}$ °E., 86 lks.
dist. mkd. $\frac{1}{4}$ S26 BT.

Fd. OK - Daniel Baker - for: Waggoner - 10/20/95 - M 119-75
(Cont. Next Page)

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - July 14, 1997 - C.S. 64/75-25

Mon. Fd.- 2½" dia. Brass cap on a 1½" O.D. iron pipe,
protrudes 15" above ground. 1962

New Bt's- Both BT's from 1961 M21-29 now gone
36" now 36" dia. 4' high D.Fir stump, with an
unhealed single blaze, scribing visible "¼ S26
CS BT", (rec. N.76°E., 98.2') 1962 DCSO
24" dia. 3' high D.Fir stump with scribing visible
"¼ S26 BT", bears N.63°E., 56.8' (agrees with
rec.) 1963 BLM

New Accessories -

4" dia. D.Fir, double blazed and scribed "X BT",
bears N.37°W., 24'.

13" dia. Maple, double blazed and scribed "¼ S35 CS
BT", bears S.48°E., 44.1'.

20" dia. D.Fir, single blazed and scribed "¼ S26 CS
BT", bears N.1½°E., 54'.

6" dia. D.Fir, double blazed and scribed "¼ S35 CS
BT", bears S.18½°W., 38.2'.

Fd. & used on BLM rehabilitation of certain corners, Timothy
J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying
Tech., under Group #2000, 2100, & 2300, Surveyed June 2004, -
(DCSO records Vol. 55 Page(s) 21498) See 2008 plat
NAD 1983 (CORS)

Latitude 43°21'33.47"N

Longitude 123°15'23.77"W