

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 and 26

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Elder & Gile, Contract #31 dated April, 1853

-
- A Fir 28" dia. bears S.5¼°W., 155 lks. dist.
- A Fir 20" dia. bears N.68¼°W., 129 lks. dist.
- A Fir 10" dia. bears N.65½°E., 88 lks. dist.
- A Fir 14" dia. bears S.83¼°E., 65 lks. dist.

Donald A. Bentz, For: Joe Denley, March 1970 - M 33-71

This corner is located S.7°W., 19.0 ft. from fence corner
4.0 ft. South of an E-W fence & approx. 100 ft. West of
reservoir. Set by double proportion.

- Set - 5/8" Iron Rod at corner from which:
- 10" Fir S.43½°W., 33.3 ft. mkd. T25SR5W S26 BT.
 - 12" Fir S.36½°E., 68.0 ft. mkd T25SR5W S25 BT.
 - 12" Fir N.69°E., 27.0 ft. mkd. T25SR5W S24 BT.
 - 8" Fir N.30°W., 54.5 ft. mkd. T25SR5W S23 Bt.

Found OK, Sept. 1996 by K.Hoffine - M 126-5

Fd. OK - Douglas Co. Surveyors Office - Randall W. Smith -
Stephen J. Flause - July 1997 - C.S. File 64/79-9

Fd. Ok by Carl Sweeden, Aug. 2004 - M145-30

DCSO-GIS Corner visitation - 8/9/2004 - Typed: 1/24/2011 -
C.S. File 67/33-1

-
- Monument - 5/8" rebar
 - Comment - OK