

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36 of T24-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder, Contract #31 dated April, 1853 (DCSO records Vol. 7 Page(s) 3085-86)

Set post cor. to Secs. 35,36,1 & 2, from which
A Y.Oak 12" dia. bears S.30°E., 33 lks.
A Y.Oak 14" dia. bears S.47°W., 112 lks.
A W.Oak 6" dia. bears N.60°E., 84 lks.
A Y.Oak 16" dia. bears N.47°W., 120 lks.

Wm. F. Briggs, Volume 1 Page 31, For: Hall & Jones
March 1884

Set post from which
A W.Oak 5" dia. bears S.65°W., 46 lks.
A W.Oak 4" dia. bears S.9½°E., 80 lks.

G.G. Stewart, Deputy - For: T.J. Medley & R.R. Clarke, et al
Jan. 16, 1922 - Volume 3 Page 110

Find two original BTs:
B.O. bears NW 79.2 ft.
8" Fir bears N.67°E., 37.0 ft.
I reset this corner with a squared 4" Fir post. Marked &
blazed new BTs:
18" Fir bears S.62°W., 62.5 ft.
18" Fir bears S.57°E., 73.0 ft.

James W. Byron, Milo Godfrey, Clete Putnam, Douglas Co.
Surveyors Office - March 4, 1960 - C.S. File 49/124-31

Found - No trace of original BTs found.
Stewart's BT, a 18" now 33" Stump S.62°W., 62.5 ft.
previously opened, shows good scribing "CS".
18" now 30" Fir stump S.57°E., 73.0 ft. shows good
scar, I do not open.
8" now 22 Fir N.67°E., 37.0 ft. shows good scribing
"W".

Distances to BTs recorded by Stewart are measured on slope.
Set - Brass cap at cor. mkd. County Surveyors Office 1960

S35|S36 T24S
S 2|S 1 T25S R5W

(Cont. Next Page)

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36 of T24-5

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

New BTs - 8" R.Fir bears N.79°W., 43.6 ft. scribed S35 T24S
R5W CS BT.
11" R.Fir bears S.5°W., 45.6 ft. scribed S 2 T25S
R5W CS BT.
9" R.Fir bears S.42°E., 50.8 ft. scribed S 1 T25S
R5W CS BT.

B.C. found, 7/84, Burt Holt - three R.Firs now burned stumps,
& 22" Fir, N.67°E now burned snag. M 97-24

FD BC by R. Dolan, 7/94 - M 120-61

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - June, 16, 1997 - C.S. 64/75-9

Mon. Fd.- 2½" brass cap on a 1½" O.D. iron pipe protrudes
14" above ground. (1960)

Accessories Fd.-

18" now 26" dia. 3' high rotted D.Fir stump, with
a burnt out upper blaze, we open lower blaze
and find scribing "BT", bears S.63°W., 60.6'
(rec. S.62°W., 62.5' dist. is a slope.
measurement) 1922.

8" now 22" dia. 6' high rotted D.Fir snag, with
a previously opened burnt blaze, no scribing
visible, bears N.64°E., 35.7' (rec. N.67°E.,
37' dist. is a slope measurement) 1922.

8" now 6" dia. 1' high rotted and burnt D.Fir
stump no blazes or scribing found, bears
N.75°W., 43.6' (rec. N.79°W., 43.6') 1960.

No other BT's from 1960 fd.

No Bt's from 1884 fd.

No Orig. Bt's fd.

New Accessories -

4" madrone, double blazed and scribed "X BT",
bears S.43°W., 30'.

5" madrone, double blazed and scribed "T24S R5W
S36 CS BT", bears N.56°E., 9.8'.

6" B.Oak, double blazed and scribed "T25S R5W S1
CS BT", bears S.25½°E., 25.5' to center of
scribed westerly trunk of double based tree.

7" madrone, double blazed and scribed "T24S R5W
S35 CS BT", bears N.46°W., 25.5'.

Corner lies at the intersection of a fence corner. Fence runs
south and east.