

TOWNSHIP 25 RANGE 05 POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Deputy Surveyor under Contract
#152 dated June 3rd., 1871

Set 1/4 Sec. Post, from which
 A Fir 50" dia. bears N.85°E., 28 lks. dist.
 A Fir 12" dia. bears S.41°W., 2 lks. dist.

Donald A. Bentz, For: Joe Denley - March 1970 - M 33-71

This corner is 1.5 ft. South of E-W fence line.
Set - 5/8" Iron Rod at corner from which:
 A 7" Fir N.13°W., 32.2 ft. mkd. 1/4 S25 BT.
 A 13" Fir S.29°E., 167.5 ft. mkd 1/4 S36 BT.

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - July 10, 1997 - C.S. 64/75-26

Mon. Fd.- 5/8" I.R. protrudes 8" above ground (1970)
Bt's Fd.- No OBT's found
 13" now 24" dia. 3' high D.Fir stump, with a fully
 healed single blaze, bears S.29°E., 70.3'
 (rec. S.29°E., 167.5') 1970.
 7" now 21" dia. D.Fir, with a fully healed single
 blaze, bears N.13°W., 32.2' (agrees with rec.)
 1970.

New Accessories -
 5" dia. D.Fir double blazed and scribed "1/4 S25 CS
 BT", bears N.32°E., 9.7'.
 13" dia. D.Fir double blazed and scribed "1/4 S36 CS
 BT", bears S.79°W., 33.2'.
 10" dia. D.Fir double blazed and scribed "1/4 S25 CS
 BT", bears N.89 1/2°E., 15'.

Corner lies 1.5' south of an E-W fence line