

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 056010

PRIMARY CORNER DESCRIPTION NE Cor. David Hurst DLC #56

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Addison R. Flint, Contract #28 dated April, 1854 - (DCSO DLC records Page 240)</p> <p>-----</p> <p>Set post, deposited stone 6x4 Raised mound with trench as per instructions.</p>
<p>F.C. Frear, Dep. Co. Surveyor - 4-1918 (added 6/14/2022) - Old Vol. 3 Pg 45</p> <p>-----</p> <p>Mentions NE Cor. Of Cl No. 56 and a rock.</p>
<p>Douglas Co. Surveyors Office - Milo Godfrey - July. 1962 - C.S. File 49/123-19</p> <p>-----</p> <p>Fd. fence cor., only - fences N.S. & West. No rock fd. <u>REPORTED AS NOT FOUND</u></p>
<p>Bruce Shaner for Woodruff Family Trust, July 1997 - M 124-59 & C.S. File 65/15-10B</p> <p>-----</p> <p>Found - Charred oak post, badly rotted, but probably original post set by U.S. G.L.O. in 1860. This was in same position of "rock" found by Frear in 1918 and was found (buried) by us when we were about to reset D.L.C. corner based on Frear's 1918 survey.</p> <p>Set - 5/8" x 30" iron rod with 1½" alum. cap marked "Shaner Engr RLS 430" alongside found charred oak post.</p> <p>New Accessories - 6 foot steel fence post, I set North, 1.0 ft. 6 foot steel fence post, I set East, 1.0 ft. Fence corner post bears North, 17.0 ft. (fence runs N,S & W) (corner set is on N-S fence line)</p> <p>No bearing trees within reasonable distance.</p>
<p>1</p>