

PRIMARY CORNER DESCRIPTION S.E. Cor. Gilbert DLC #61

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #28 dated April, 1854

Set post, from which

A W.Oak 30" dia. bears N.40°E., 18 lks.

A B.Oak 22" dia. bears S.62°W., 45 lks.

Don E. Garrett, For: Mrs. Paul Thinger - Sept. 1968
Map file M 36-34

Found - 36" Oak stump, shows good reverse face. S.E. Cor.
DLC #61 bears S.40°W., 18 lks.

Set - 5/8" Iron Rod.

BTs - 6" W.Oak bears S.74°24'W., 28.5 ft.

6" B.Oak bears S.31°E., 40.8 ft. scribed S.E. Cor.
DLC 61 BT.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flaue
- Nov. 20, 1997 - C.S. 64/78-30

Mon. Fd.- bent 5/8" I.R., protrudes 6" above ground.

Bt's Fd.- 30" now 32" dia. 3' high rotted oak stump, no
scribing visible bears N.40°E., 11.9' (agrees
with rec.) OBT.

6" now 8" dia. W.Oak, with a fully healed 4' high
single blaze, bears S.31°E., 40.8' (agrees
with rec.) 1968.

6" now 11" dia. 1' high W.Oak stump showing
evidence of a healed lower blaze, bears
S.74½°W., 28' (rec. S.74°24'W., 28.5') 1968.

Mon. set- 2 3/8" dia. brass cap on a 1 3/8" O.D. by 32" long
iron pipe is set at plumb position of fd.
bent I.R., protrudes 10" above ground. Found
I.R. set along north edge of BC/IP protrudes
6" above ground.

Douglas County Surveyors Office

T 25 S SE COR | R

DLC | 6

61 | W 1997

New Accessories -

10" dia. B.Oak, double blazed and scribed "SE
DLC 61 CS BT", bears N.15°E., 5.3'.

14" dia. W.Oak, double blazed and scribed "SE
DLC 61 CS BT", bears N.67½°W., 33.5'.

8" dia. W.Oak, double blazed and scribed "SE
DLC 61 CS BT", bears S.51°W., 50.4'.

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 061040

PRIMARY CORNER DESCRIPTION S.E. Cor. Gilbert DLC #61

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Found OK by C. Sweeden, Sept. 2000 - M 135-57