

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 & 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3850-3851)

Marked a Cedar 60" dia. for ¼ sec. cor., from which
A Fir 48" dia. bears N.50°E., 11 lks. dist.
A Fir 8" dia. bears S.55°E., 50 lks. dist.

C.W. Springer, Surveyor - For: M.F. DeCosta - June 25, 1923
Volume 3 Page 159 and Field Book 52 Page 12

I find the 60" Cedar for ¼ sec. cor. as described in Gov't
Field notes. One orig. BT down, other standing. I open the
good BT for proof to the interested parties of the corner
and Mark:

10" W.Fir N.36°30' W., 21.0 ft.
18" W.Fir S.55°00'E., 52.5 ft.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy & Mike
Stone - July & August, 1963 - C.S. File 49/123-99

Found - Burned, hollow shell of large Cedar snag in 3-way
fence corner, (fences East, West & south). No
markings left on Cedar.
Remnants (in place) of large Fir stump N.50°E.,
approx. 7 ft.
No trace of orig. SE tree.
No trace of either BT. mkd. in 1923 renewal.

Note, a small pond bears west from cor. approx. 4 chains dist.
(See orig. field notes) Also see affidavit of Guy Cole in
field notes in C.S. File 49/123.

Set brass cap at cor. (inside shell of old Cedar) mkd: ¼ S 6
County Surveyors Office 1963 T25S R6W S 7

New BTs - 6" D.Fir N.55°E., 7.0 ft. mkd: ¼ S6 CS BT.
14" I.Cedar S.79°W., 39.6 ft. mkd: ¼ S7 CS BT.

Found OK, B. Shaner - July 1989, R.M. 3-72

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J.
Flause - 2/11/98 - C.S. File 64/79-30

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe,
protrudes 14" out of hollowed out 1 ft. high
60" dia., Cedar stump. 1963 BC/IP & Orig.
corner tree.

(Cont. next page)

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

No OBTs Fd.
No BTs from 1923 Fd.
6" now 17" dia., D.Fir with a fully healed double blaze, bears N.55°E., 7.0 ft. (Agrees with Rec.) 1963
14" now 20" dia., I.Cedar with a fully healed double blaze, bears S.79°W., 39.6 ft. (Agrees with Rec.) 1963
New BTs- 9" dia., G.Fir, double blazed and scribed "¼ S6 CS BT" bears N.88°E., 24.0 ft.
10" dia., D.Fir, double blazed and scribed "¼ S7 CS BT" bears S.9½°W., 9.2 ft.
Note - Corner lies at the intersection of fences with old down fence wire running South and West and new fence running Easterly. See sketch in file.