

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec Cor for 17, 18, 19 and 20

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
(DCSO records, Volume 9 Page 3842-43)

-----  
Set post cor. to secs. 17, 18, 19 and 20, from which  
A Y.Oak 14" dia. bears S.39°W., 34 lks. dist.  
A Y.Oak 6" dia. bears S.85°E., 23 lks. dist.  
A Y.Oak 9" dia. bears N.27°E., 33 lks. dist.  
A Laurel, 12" dia. bears N.53°W., 84 lks. dist

Milo E. Godfrey, Dep. Co. Surveyor - Mike Stone, Chainman  
October 15, 1962 - C.S. File 49/123-35

Found - 3/4" Iron rod at corner. (possible source of I.R.:  
G.G. Stewart, C.S. File 17/35, Jan. 1923,  
says "Set Stake from Orig. BTs"- P.C. Armstrong  
May 1950 in C.S. File 40/332, says "3/4 in.  
Iron Rod" but not whether set or found.)  
Laurel, dead, N.53°W., 55.4 ft. The entire southeast  
side of this tree has been burned away.  
Stump hole N.27°E. 21.8'. No traces of wood remain  
Stump hole S.39°W. 22.4 ft. No traces of wood remain  
No trace of SE BT.

For proof of corner location, see Mr. Don K. Baird's affidavit  
on renewal notes in CS File 49/123.

Alongside 3/4 Rod at cor., Set brass cap mkd: County Surveyor's  
Office, 1962 T25S R6W S 18 | S 17  
S 19 | S 20

Corner lies in E. & W. fence line. No live trees in any  
direction within reasonable distance.

Found Feb. 1981, R. Dolan - M 86-43  
Fd. Ok by Carl Sweeden, - Aug. 1998 - M130-22.  
Fd. OK by C. Sweeden, Aug. 2001 - M138-61

DCSO-GIS Corner visitation - 7/1/2004 - Typed: 1/24/2011 -  
C.S. File 67/33-1

-----  
Monument - 1.25" BC/IP  
Comment - (needs) rehab

Fd. BC, not BTs 1/2025 - by N. Hibbs M185-26