

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Henry S. Gile, Contract #31 dated April, 1853
(DCSO Records, Volume 9 Page 3826)

Set post cor. to secs. 2, 3, 10 and 11, from which
A W.Oak 12" dia. bears S.64°E., 124 lks. dist.
A Y.Oak 18" dia. bears N.59°E., 110 lks. dist.
A W.Oak 12" dia. bears N.22°W., 7 lks. dist.
A Y.Oak 20" dia. bears S.35°W., 22 lks. dist.

G.G. Stewart, For: J.A. Leatherwood, March 22, 1922
C.S. File 2/14; Vol. 3 Page 112

Found - A 12" W.Oak S.64°E., 82.0 ft.
Stump of B.Oak S.35°W., 14.5 ft.
Set - A sandstone for cor. with + cut on it for corner
common to 2, 3, 10 11.
BTs - 6" Pine S.15°W., 135.0ft.
12" W.Oak S.64°E., 82.0 ft. (Orig. BT)
16" W.Oak N.38°E., 116.0 ft.
No other trees suitable.

Milo E. Godfrey, Deputy Co. Surveyor; - Mike Stone
October, 1962 - C.S. 49/12327

Found - Sandstone rock with "X" cut in top. (Stewart)
19" W.Oak S.64°E., 81.8 ft. chopped scar open &
found good scribing.
Rotten Oak stump S.35°W., 14.5 ft. No marks re-
maining.
No trace found of other 2 orig. bearing trees.
20" W.Oak N.38°E., 116.0ft. good axe scar plainly
visible.
20" Pine S.13°W., 135.5 ft. Scar visible. Reblaze &
scribe this tree "T25S R6W S10 CS BT".
Set brass cap at cor. alongside rock mkd: County Surveyor's
Office, 1962 S 3 | S 2
T25S R6W S10 | S11
New BTs - 9" W.Oak S.43°E., 19.4 ft. mkd. T25S R6W S11 CS BT.
16" Madrone N.42°W., 163.5 ft. mkd. T25S R6W S3 CSBT
Cor. lies in N & S fence line approx. 250 ft. North of State
Hwy #38.

Fd. BC & 5 BTs, 1972 Dependent Resurvey, BLM (DCSO records
Volume 36 Page 14999-15000)

continued next page

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2, 3, 10 and 11

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

DCS0-GIS Corner visitation - 6/30/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok

FD. BC. by James Stanley, May 2009 - ST HWY 138-010D