

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 540100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35; & 2 of T26-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3809)

Set ¼ sec. post, from which
 A Fir, 8" dia. bears N.32°E., 46 lks. dist.
 A Cedar 16" dia. bears S.21°E., 103 lks. dist.

Milo E. Godfrey's Crew - Vernon Tracy; Mike Stone
June 27, 1963 - C.S. File 49/123-82

Found - 46" Fir stump N.32°E., 30.4 ft. Cut open & found one
 scribe mark "l". Tree had been opened
 previouly & grown over again. Balance of upper
 face rotted.

No trace of Cedar to S.E.
Set - Brass cap at cor. mkd: County Surveyors Office 1963
 T2S R6W ¼ S $\frac{35}{2}$

New BTs - 15" W.Fir N.48½°E., 66.2 ft. mkd. ¼ S35 CS BT.
 9" D.Fir S.58°W., 78.5 ft. mkd. ¼ S 2 CS BT.

Note - Corner falls in E. & W. fence line 33 ft. west of small
stream.

Found OK by Mark Smalley, LS # 2354 - For: Roseburg Resources
Co. -Feb. & Mar. 1993 - M 117-7.

Mark Smalley, July 1995, M 119-67

Found - 1963 County BCIP
 26" fir N.48½°E., 66.2' healed.
 20" fir S.58°W., 78.5' healed.
New BT's- 18" fir N.82°W., 21' "¼ S BT"
 10" fir S.35°E., 18.8' "¼ S BT"

Fd. OK - Kristian DeGroot - Nov. 1995 - M 123-15