

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 600240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 25 and 26

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, contract #31 dated April, 1853  
(DCSO records, Volume 9 Page 3817)

-----  
Set ¼ sec. post, from which  
    A Y.Oak 20" dia. bears N.83½°W., 38 lks. dist.  
    A Y.Oak 12" dia. bears S.50°E., 20 lks. dist.

Milo E. Godfrey, Dep. Co. Surveyor - Vernon Tracy; Mike  
Stone - January, 1963 - C.S. File 49/123-65

-----  
Found - 12" B.Oak S.50°E., 13.2 ft. down & rotten, face  
          with good reverse scribing.  
          Rotten base of Oak stump N.83½°W., 25.1 ft. no  
          marks found, portion found below ground sur-  
          face only.

Set brass cap at cor. mkd: County Surveyor's Office, 1963  
                                  T 25 S R 6 W ¼ S26|S25

New BTs - 10" D.Fir N.75°W., 6.9 ft. mkd: ¼ S26 CS BT.  
          10" D.Fir S.75°E., 14.0 ft. mkd: ¼ S25 CS BT.

Corner lies on fairly steep NW slope.

Fd. brass cap, L. Dolan, Sept. 1991, MLP 1991 - 0053

DCSO-GIS Corner visitation - 7/8/2004 - Typed: 01/25/2011 -  
C.S. File 67/33-1

-----  
Monument - BC/IP 1.25"  
Comment - (needs) rehab