

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23, 24, 25 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3817)

Set post cor. to secs. 23, 24, 25 and 26, from which
A Y.Oak 14" dia. bears N.41°E., 34 lks. dist.
A Y.Oak 15" dia. bears N.45°W., 57 lks. dist.
A Y.Oak 10" dia. bears S.52½°W., 58 lks. dist.
A Y.Oak 18" dia. bears S.60°E., 23 lks. dist.

Ben B. Irving, Deputy Co. Surveyor - Witnesses, Emmett Hall
Jake Roth - January 28, 1924 - "Old" Cor. renewal book, Pg.
56 (also, C.S. File 2/25A for some notes)

One original BT standing in excellent shape. One orig. BT
chopped open; tree dying. One orig. BT hollow & dying. Stump
properly located for 4th BT badly rotted.
Set 1" Iron pipe 30" long, from which:
24" B.Oak N.41°W., 37.0 ft. (this recorded orig. N.45°W
& one N.41°E which had apparently been reversed)
8" W.Oak S.44°44'W., 71.0 ft.
30" B.Oak S.18°04'E., 81.7 ft.
6" W.Oak N.75°40'E., 64.8 ft.

Milo E. Godfrey, Deputy County Surveyor - V. Tracy; Mike
Stone - December 1962 - C.S. File 49/123-60

Found - ¾" Galv. I.P. at corner.
24" B.Oak N.41°W., 37.0 ft. shows good scar. Tree
dying.
10" W.Oak S.44¾°W., 71.0 ft. Cut open & found good
scribing "S".
30" Oak stump S.18°E., 81.7 ft. Portion of straight
scribe mark visible on old face, not grown over
10" W.Oak N.75½°E., 64.8 ft., shows good scar.
Only trace fd of original BTs were stump holes to
NE and SE.
No trace found of orig. SW tree.

DID NOT SET BRASS CAP.

New BTs - 16" W.Oak N.47½°W., 70.5 ft. mkd. T25S R6W S23 CSBT
15" D.Fir S.61°W., 9.3 ft. mkd. T25S R6W S26 CS BT.
8" W.Oak S.86°E., 31.3 ft. mkd. T25S R6W S25 CS BT.
8" D.Fir N.55½°E., 74.3 ft. mkd. T25S R6W S24 CS BT
A North & South fence line bears West 8.5 ft.