

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec Cor for 1 & 2; 35 & 36, T24-6

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records Volume 8 Page 3131)

Set post cor. to secs. 35, 36, 1 & 2, from which
A Y.Oak 15" dia. bears S.1°E., 108 lks. dist.
A Y.Oak 20" dia. bears S.57°W., 99 lks. dist.
A Y.oak 14" dia. bears N.65¼°W., 177 lks. dist.
A Y.Oak 14" dia. bears N.73¾°E., 285 lks. dist.

C.W. Springer, Deputy Co. Surveyor; H.E. Bergh; W.A. Davison;
F.A. Bemis; For: Davison & Bemis - February, 1923
Volume 3 Page 138 & Field Book 60.

Reset from 2 original BTs and a stump which witnesses said
bore scribe marks before a fire swept by it. Also found a
third O.B.T. later. Set an iron pin in ground from which,
A B.Oak 15" dia. bears S.1°E., 108 lks.
A B.Oak 14" dia. bears N.65°W., 177 lks.
A B.Oak stump 12" dia. bears S.59°W., 100.7 lks.
A B.Oak 14" dia. bears N.73¾°E., 285 lks.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon R. Tracy; Mike
Stone - December 3, 1962 - C.S. File 49/123-55

Found - 2" steel shaft set by Springer, 1923, top of shaft
4" below surface.
Rotted remnants of old Oak, in place, N.65¼°W.,
116.8 ft. Good reverse scribing.
31" B.Oak N.73¾°E., 184.3 ft. (not 188.1 ft.) shows
2 good scars, tree alive & in good condition.
No trace of SE or SW trees.
Set brass cap at cor. mkd: County Surveyor's S35|S36 T24S
Office 1962 S 2|S 1 T25S R6W
New BTs - 15" D.Fir S.52°W., 21.4 ft. mkd. T25S R6W S2 CSBT.
7 W.Oak S.29°E., 8.4 ft. mkd: T25S R6W S1 CS BT.
10" B.Oak N.34°E., 11.1 ft. mkd: T24S R6W S36 CSBT.
10" D.Fir N.41½°W., 43.0 ft. mkd: T24S R6W S35 CSBT.
Cor. lies in fence cor., old fences N., S. & West from corner.

Found and tied, BLM Dependent Resurvey, June 1972
DCSO records, Volume 36, Page 14997

Found OK by K. Hoffine, March 2000 - M134-64