

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 36; & 1 of T26-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853
(DCSO records, Volume 9 Page 3809)

Set ¼ sec. post, from which
 A Y.oak 16" dia. bears S.27½°E., 52 lks. dist.
 A Y.oak 12" dia. bears N.36½°W., 80 lks. dist.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy and
Mike Stone - June & July 1963 - C.S. File 49/123-80

Found - Stump hole & rotten remains of Oak log N.36½°W.,
 53.8 ft. In rotten wood found old flattened
 areas appearing to be portions of old face,
 no scribing found.
 Stump hole S.27½°E., 34.3 ft. No portion of tree
 remaining.

This location also fits call in gov't field noted for ridge
top. Corner position lies in E. & W. fence line 3 ft. west
of fence corner (fences East, West and North.)

Set - Brass cap at cor. mkd. County Surveyors Office 1963
 T25S R6W S 36
 T26S S 1

New BTs - 6" D.Fir N.9°E., 18.2 ft. mkd. ¼ S36 CS BT.
 5" W.Oak S.5°E., 19.0 ft. mkd. ¼ S 1 CS BT.

MARK SMALLEY, JULY 1995, M 119-67 - FOR ROSEBURG RESOURCES

FOUND - 1963 County BCIP in fence corner
 11" fir, N.9°E., 18.2' healed.
SCRIBED - 8" oak, N.15°W., 15.3' "¼ S BT"
 22" fir, N.76°E., 25.3' "¼ S BT"
 17" fir, S.85°W., 18.2' "¼ S BT"

DCSO-GIS Corner visitation - 7/8/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok