

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION Tsp. Cor. (SE Cor. Sec. 36)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Tps. 25 & 26, South between Ranges
5 & 6 West
Drove charred stake & raised mound with trench and pits as
per instructions.

Milton L. Baldy - For Don Calpin & O.C. Seiter - "Oregon Pear
Co. Plat A" (now vacated) Volume 3 Page 22 - Jan. 1911

Set Galv. I.P. 2" x 36", driven 6" below the surface at the NW
corner Section 6.

James W. Byron, Deputy, For: Ed Russell - April, 1955
C.S. File 47/12

Found - 1½" Iron pipe at fence intersection. Use 1½" I.P.
for Sec. Cor. (See Vacated Plat, Oregon Apple
& Pear Co. Plat A, Vol. 3 Pg. 22, Initial Pt.)
All orig. BTs gone. (I could find none ever listed. 8/91 V.L.)
Blazed & Scribed:
10" R.Fir N.17°E., 146.0 ft. S31 T26S R5W CS BT.
16" R.Fir (stool of) S.84°E., 600.0 ft. S6 T26S
R5W CS BT.
No other trees near.

BLM Dependent Resurvey, C. Albert White; Donald R. Beck;
May 3-24, 1963 (DCSO records Volume 32 Page 13361-2

Corner was determined at the intersection of old wire fences
which extend N. and W. at the SE corner of an old orchard
from which bearing trees by Byron, Deputy Co. Surveyor, 1955,
A Fir, 18" dia. bears N.20°E., 224 lks. dist. mkd. with
A healed blaze, facing the corner.
A fork of a Fir, 25" dia. bears S.85°E., 910 ft. dist.
mkd. with a healed blaze, facing the corner.
Set an iron post 28" long 2½" dia. 24" in the ground, with
brass cap mkd.

T 25 S
R 6 W R 5 W
S 36 | S 31
S 1 | S 6
1963

No suitable trees available in secs. 1 and 36 within limits.
(Cont. next page)

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700100

PRIMARY CORNER DESCRIPTION Township Cor. - SE Cor. Sec. 36

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Found OK, Donald Bentz - Sept. 1986 - M 102-48 & M 106-4
Found OK, M. Smalley - July 1995 - M 119-67

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/11/98 - C.S. File 64/79-26

Found - 3½" dia., brass cap on a 2½" O.D. iron pipe, protrudes 5" above ground. 1963 BLM
10" now 41" dia., D.Fir with fully healed blazes, bears N.18½°E., 146.0 ft. (1955 rec. N.17°E., 146.0 ft.) 1955 DCSO
16" now 30" dia., triple trunked down D.Fir with a fully healed blaze root hole near. (Rec. S.84°E., 600.0 ft) 1955 DCSO
New BTs- 30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.13°W., 427.0 ft.
30" dia., D.Fir, bark scribed "T25S R6W S36 CS BT" bears N.60°E., 324.0 ft.
Note - Corner lies at the intersection of fences running East, West, & North. No trees south of line. See sketch in file.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 01/25/2011 - C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - ok