

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Sec Cor for 24 & 25; 19 & 30, T 25-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Sec. 19, 24, 25, & 30, from which
A Laurel 15" dia. bears S.71°W., 161 lks.
An Ash 18" dia. bears S.47°E., 37 lks.
An Ash 10" dia. bears N.1°E., 25 lks.
A W.Oak 12" dia. bears N.62°W., 59 lks.

Francis L. Ingram, Douglas Co. Surveyor - John Powell & Crew
May 1972 - C.S. File 56/16 and M 42-61

This corner set from survey of Range line.
Set brass cap at cor. mkd. County Surveyors R T 25 S R
Office 6 S 24 S 19 5
1972 W S 25 S 30 W
New BTs - 24" Cedar S.23°W., 70.8 ft. scribed T25S R6W
S25 CS BT.
11" D.Fir S.81°E., 21.8 ft. scribed T25S R5W
S30 CS BT.
9" D.Fir N.26°W., 23.7 ft. scribed T25S R6W
S24 CS BT.
No good trees in N.E. Quad.

Max Hull, Oct. 1993 - M119-6; CS 63/115.

Found bearing trees per M42-61, pipe & brass cap missing.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 3/31/1999 - C.S. File 66/8-35 & M131-50

Found - No monument found.
Bearings & distances taken from new corner position
24" now 31" dia., Cedar with a fully healed double
blaze, bears S.32½°W., 56.6 ft. 1972
11" now 21" dia., D.Fir with a fully healed double
blaze, bears N.47¼°E., 24.0 ft. (Blaze faces
West) 1972
9" now 16" dia., D.Fir with a fully healed double
blaze, bears N.19 3/4°W., 41.5 ft. 1972
Set - 2 3/8" dia., brass cap on a 1 3/8" o.d. by 32" long
iron pipe is set at new proportioned corner
position. Protrudes 6" above ground, mkd:
DOUGLAS COUNTY SURVEYORS
T25S
R S 24 S 19 R
6 S 25 S 30 5
W 1999 W
OFFICE

continued next page

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700300

PRIMARY CORNER DESCRIPTION Cor. Secs 24 & 25; 19 & 30 T25-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

5" Cedar double blazed and scribed "X CS BT" bears
S.72°E., 16.1 ft.
Note - Corner lies 6½ ft. East of a N-S fence line.

Fd. OK by C. Sweeden, Sept. 2000 - M135-54

Russell Badgley - For: Jon Martz - 10/2021 - 2021-0047B

Found - 1 3/8" iron pipe bent at ground by logging activity
in skid road. I remove, straighten, & reset plumb
over the flanges; From which BTs by DCSO in 1999:
A 37" Cedar bears S.32°00'W., 56.8' (S.32½°W. 56.6')
A 26" D.Fir bears N.48°15'E., 24.1' (N.47¼°E. 24.0')
A 21" D.Fir bears N.20°00'W., 41.0' (N.19¾°W. 41.5')
A 9" Cedar bears S.72°00'E., 16.1' (S.72°E., 16.1')