

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 24; & 19 of T25-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853  
-----

Set 1/4 Sec. cor post, from which  
A W.Oak 14" dia. bears S.48 1/2°W., 638 lks.  
A W.Oak 18" dia. bears S.5 1/4°W., 849 lks.  
No other trees in proper section.

Francis L. Ingram, Douglas Co. Surveyor - John Powell & Crew  
May 1972 - C.S. File 56/16 and M 42-61  
-----

This corner set from survey of Range line.  
Set brass cap at cor. mkd. County Surveyor's R T 25 S R  
Office, 1972 6W S 24 | S 19 5W  
New BTs - 14" D.Fir N.65°E., 35.6 ft. scribed 1/4 S19 CS BT.  
6" D.Fir S.9°W., 33.5 ft. scribed 1/4 S24 CS BT.  
Old fence corner bears N.47°E., 10.0 ft.

Douglas Co Surveyors Office - Randall Smith & Stephen Flause -  
Oct. 9, 1997 - C.S. 64/78-11  
-----

Found - No monument found  
14" now 25" dia. D.Fir, with a fully healed single  
blaze, bears N.65°E., 35.6' (agrees with  
rec.) 1972  
6" now 21" dia. D.Fir with a fully healed single  
blaze, bears S.6°W., 33.5' (rec. S.9°W.,  
33.5') 1972  
Set- 2 3/8" dia. Brass cap on a 1 3/8" O.D. by 32" long  
iron pipe is set from 1972 BT's protrudes 8"  
above ground.

DOUGLAS COUNTY SURVEYORS

T 25 S

R 1/4 R  
6 S 24 | S 19 5  
W 1997 W

OFFICE

7" dia. Ash, double blazed and scribed "1/4 S24 CS  
BT", bears N.13°W., 9.5'.  
7" dia. Ash, double blazed and scribed "1/4 S24 CS  
BT", bears N.68°W., 16.8'.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -  
Stephen J. Flause - 3/31/1999 - C.S. File 66/8-35 & M131-50  
-----

Found - 2" alum. cap on a 5/8" iron rod protrudes 1" above  
ground, mkd:  
continued next page

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 19, T25-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

T25S  
R6W R5W  
¼  
S 24 | S 19  
1999  
PLS 1941

2 3/8" DCS0 brass cap on a 1 3/8" O.D. iron pipe protrudes 8" above ground, 1997, bears N.15°W., 35.06 ft., from alum. cap/IR.  
Bearings & dist. taken from 1999 alum cap/IR  
14" now 25" dia., D.Fir with a fully healed single blaze bears N.25¼°E., 54.1 ft., (Note blaze faces S.65°W.) 1972  
6" now 21" dia., D.Fir with a fully healed single blaze N.87½°W., 12.6 ft. (Note blaze faces North) 1972  
7" now 7" dia., Ash with an unhealed double blaze scribing visible "¼ S24 CS BT", bears N.14½°W., 44.6 ft. 1997

Removed- 1997 DCS0 brass cap is sawn off, iron pipe and a yellow plastic cap set in center, iron pipe protrudes 6" above ground.

Note - Corner lies 10 ft. west of centerline of drive way.  
This renewal reflects recent survey by PLS 1941 (Kris DeGroot, BTS) that determined corner position based on old subdivision ties.

Fd. by ODOT 1/7/2009 - C.S. File 65/66-2