

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 100509

PRIMARY CORNER DESCRIPTION SE Cor. Sec. 12, T. 25-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Original - A.R. & S.C. Flint, under Contract #392 dated May 26, 1881 (DCSO records, Volume 9 Page 3900)

Set Hemlock post, 4 ft. long, 4" sq. firmly in the ground, from which

- A Fir 8" dia., bears N.50°E., 27 lks. dist.
- A Fir 48" dia., bears S.85°W., 12 lks. dist.
- A Fir 8" dia., bears N.5°W., 11 lks. dist.
- A Fir 30" dia., bears S.65°E., 27 lks. dist.

GLO survey by William P. Heydon, under Contract #656, dated May 21, 1896 (DCSO records, Volume 9 Page 3911)

Intersect W. bdy of Tp. 10.00 chs. S of cor. to secs. 7, 12, 13 and 18, which is a Hemlock post firmly set in the ground marked and witnesses as described by the Surveyor General. I obliterate marks on post and bearing trees referring to secs. in R. 7 W.

At point of intersection, set a Fir post, 3 ft. long, 4" sq., 24" in the ground for closing corner for Secs. 7 and 18 mkd. C.C. T25S R7W on E. S7 on N. and S18 on S faces, with 4 grooves on S and 2 grooves on N faces, from which

- A Fir 18" dia., bears N.70°E., 42 lks dist. marked CS T25S R7W S7 BT.
- A Fir 10" dia., bears S.44°E., 50 lks. dist., marked CC T25S R7W S18 BT.

Doug. County Surveyors Office - Milo Godfrey, Deputy; Vernon Tracy; Mike Stone - Oct. 29, 1962 - C.S. File 49/88-9

Found - 30" Fir S.65°E., 17.8 ft., old bark scribing visible "T2 R W S18 BT". Scribing has characteristics of Flint's scribing. This scribing was supposed to have been destroyed by Heydon in 1896.

53" Fir S.85°W., 7.9 ft. No scribing found, but old axe faces on bark.

14" W.Fir N.5°W., 7.3 ft. shows 2 axe faces on bark & scribe mark "*".

No trace of original NE BT.

Set Brass cap at cor. mkd. County Surveyors T25S R8W S12
Office, 1962 S13

New BTs - 14" W.Fir S.55°W., 23.2 ft. mkd. T25S R8W S13 CSBT.
18" W.Fir N.17°W., 62.0 ft. mkd. T25S R8W S12 CSBT.

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 100509

PRIMARY CORNER DESCRIPTION SE Cor. Sec. 12, T. 25-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James Jelley, under Group # 563 - Survey, 1964 (DCSO records, Volume 33 Pages 13744-45)

The cor. of secs. 12 and 13 only, remonumented and recorded by Milo Godfrey in 1962, with an Iron pipe 1" dia., 8" above the ground, with brass cap.

from which the remaining original bearing trees
A Fir 30" dia., bears S.65°E., 27 lks. dist.
with scribe marks T 2 R and other illegible marks visible on bark blaze. (marks were reproted destroyed by Heydon in 1896)

A Fir 52" dia., bears S.85°W., 16 lks. dist. with bark blaze, no scribing visible. (Rec. 12 lks.)
and bearing trees by Godfrey

A W.Fir 14" dia., bears S.55°W., 35 lks. dist.
with scribe marks T25S R8W S13 CS BT visible on double blaze.

A W.Fir 16" dia., bears N.18°W., 94 lks. dist., with scribe marks T25S R8W S12 CS BT visible.

Add marks BLM 1964 to the bottom of brass cap.

Howard Johnstone, For: Roseburg Lumber Co. - Aug. 10, 1983
M 94-63

Found - 1962 DCSO brass cap & Iron pipe in root wad of blown down SW BT.

18" Fir S.55°W., 23.1 ft., partially healed.

22" Fir N.18°W., 62.0 ft., leaning.

52" Fir S.85°W., 10.6 ft., down.

30" Fir S.65°E., 17.8 ft., down and rotted.

Set - Reset brass cap I.P. at record bearing & distance from standing BTs.

New BT - 13" Cedar S.67°E., 28.2 ft.

Found OK by K. DeGroot, Feb. 2002 - M137-49