

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 140700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & 31 of T24-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 8 Page 3194)</p> <p>-----</p> <p>Set ¼ sec. post, from which An Oak 15" dia., bears South, 13 lks. dist. An Oak 18" dia., bears N.10°W., 19 lks. dist.</p>
<p>Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam - Marcy 25, 1960 - C.S. File 49/41-21</p> <p>-----</p> <p>Found - Orig. 18" now 26" B.Oak, center partly rotted, shows good scribing (reverse) Orig. South BT gone. Set Brass cap at cor. mkd. County Surveyor's Office, 1960</p> <p style="text-align: center;">¼ <math>\frac{S\ 31}{S\ 6}</math> T24S T25S R 7 W</p> <p>New BTs- 6" R.Fir bears S.34°E., 9.4 ft. scribed ¼ S6 CS BT. 5" R.Fir bears N.70°E., 9.0 ft. scribed ¼ S31 CS BT.</p>
<p>Fd OK, Howard Johnstone, May 1987 - M 104-16</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 2/18/98 - C.S. File 64/79-33</p> <p>-----</p> <p>Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 6" above ground. 1960 18" now 26" dia. B.Oak with a previously opened unhealed rotted blaze bears N.10°W., 12.5 ft. (Agrees with rec.) OBT 5" now 20" dia. D.Fir with a fully healed double blaze, bears N.70°E., 9.0 ft. (Agrees with rec.) 1960 6" now 6" dia., down D.Fir with a rotted blaze, roothole near record, "S.34°E., 9.4 ft." 1960 16" D.Fir with a fully healed single blaze bears S.29°W., 14.5 ft. (Agrees with Roseburg Lumber BT Tag dated 4-8-87 by F. White) This BT is not of record.</p> <p>New BT - 11" dia. D.Fir, double blazed and scribed "¼ S31 CS BT" bears N.69½°W., 17.3 ft.</p>
<p>Fd. &amp; used on BLM dependent resurvey by Bryan S. Seibold &amp; Wayne Rogers, Cadastral Surveyors, under Group #1862, surveyed Sept.-Dec. 1997 - (DCSO recs Vol. 53 Page 20303)</p>
<p> </p>