

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 173700

PRIMARY CORNER DESCRIPTION M.C. on N. Bdy Section 6

Alias <u>862570</u>	Description <u>M.C. Left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #73 dated June 8, 1857 (DCSO records, Vol. 8 Page 3194)  
-----  
Cedar 12" dia., mark same for meander post, left bank, from which  
    An Oak 10" dia., bears S.10°E., 24 lks. dist.  
    A Cedar 12" dia., bears N.45°W., 47 lks. dist.

Ronald Geisler, LS #1988, for: Champion International - Feb. thru March 1983 - M 93-79  
-----  
Set - 2½" Alum. cap set on a 7/8" x 36" Iron pipe, on west bank of Umpqua River near high water line.  
    4" Fir bears N.60°W., 9.1 ft. scribed X BT.  
    24" Fir bears N.6°E., 104.0 ft. scribed MC S31 BT.  
Note: No BTs available south of line.

Fd. & used on BLM dependent resurvey by Bryan S. Seibold & Wayne Rogers, Cadastral Surveyors, under Group #1862, surveyed Sept.-Dec. 1997 - (DCSO record Vol. 53 Page(s) 20302)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 3/5/2019 (Filed 11/17/2021) - C.S. File 67/50-15  
-----  
Found - A 2½" dia., alum. cap on a 3/4" I.D. IP, cap is properly mkd. Cap is projecting 10", pipe is rusted and cracker 2" above ground. 1983  
    A 38" dia., D.Fir with FHSB, bears N.4¼°E., 105.0 ft. (rec N.6°E., 104.0') 1983  
    A 22" dia., D.Fir with fully healed high-low blaze; bears N.54°W., 9.1 ft. (rec. N.60°W., 9.1') 1983  
BLM records  
    38" Fir N.4¼°E., (158 lks) 104.3 ft  
    22" Fir N.58°W., (13½° lks) 8.9 ft.  
New - Found mon. broken off at crack. A 5/8"x30" IR driven into IP to proj. 10" alum cap and IP set over iron rod.  
Note - Lies 50' east of Tye Access Rd centerline and west of the Umpqua River.