

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under Contract #202 dated March 11, 1874 (DCSO records, Volume 9 Page 3893)

Set Fir post for cor. to secs. 29, 30, 31 & 32, from which
A Fir 10" dia., bears N.34½°E., 25 lks. dist.
A Fir 12" dia., bears S.30°E., 57 lks. dist.
A Fir 12" dia., bears S.54°W., 47 lks. dist.
A Maple 8" dia., bears N.54°W., 40 lks. dist.

G.G. Stewart, Deputy; Wit: J.S. Germond; H.F. Roeder; N.E. Richardson - Nov. 14, 1921 - C.S. File 2/23; Field Book 35 Pg. 44; Vol. 3 Page 100

Put 1" I.Pipe for corner. (Corner was pile of rocks placed by J.S. Germond around original stake which had been burned off)
New BTs - 30" Fir N.34°E., 59.5 ft.
 12" Alder S.25°30'E., 42.0 ft.
 10" Maple S.50°W., 5.7 ft.
 10" Maple N.38°W., 9.1 ft.
Original trees destroyed by fire.

Doug. County Surveyors Office - James Byron, Deputy; M. Godfrey - Sept. 10, 1957 - C.S. File 49/10-1

Found - 1" I.P. 6" under, at corner. 1921 by Stewart.
 10" Maple S.50°W. and the 10" Maple now 18" N.38°W. show good healed blazes. I do not open.
 The 12" now 18" Alder S.25½°E., shows good but partly rotted scribing.
 The NE BT, now 36" rotted stump.
Set Brass cap alongside 1" I.P., mkd. 30|29 T. 25 S., R. 7 W. 31|32 Co. Surv Off 1957
New BTs - 14" R.Fir S.53°E., 30.1 ft. scribed T25S R7W S32 CS BT.
 16" R.Fir N.28°E., 66.8 ft. scribed T25S R7W S29 CS BT.

BLM resurvey, by G. Steven Popken, Group #869 - Survey, May/July 1975 (DCSO records, Vol. 37 Page 15308)

The sec. cor., perpetuated & recorded by G.G. Stewart in 1921 & subsequently perpetuated & recorded by Byron in 1957, with a DCSO brass cap, from which the remains of BTs by Stewart
A sawed Alder stump 22" dia., bears S.25°E., 62½ lks. dist. with fragmentary scribe marks visible on bark
A Maple 18" dia., bears S.50°W., 9 lks. dist., with healed blaze. Continued next page

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Maple 21" dia., bears N.38°W., 15 lks. dist., with healed blaze.
and the remains of BTs mkd. by Byron
A Fir snag 17" dia., bears N.27°E., 100 lks. dist., with healed double blaze.
A sawed Fir stump 15" dia., bears S.53½°E., 46 lks. dist., with healed blaze.
and new bearing trees
A Fir 14" dia., bears N.33½°E., 106 lks. dist., mkd. T25S R7W S29 BT.
A Maple 13" dia., bears S.8½°E., 84 lks. dist., mkd. T25S R7W S32 BT.

Found OK, April 30, 1979, DCSO office, C.S. 60/24-27
Fd. Ok by D. Edwards, Feb. 2006 - M149-71