

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W. H. Byars, under Contract #202, dated March 11, 1874 (DCSO records, Volume 9 Page 3894)

-----  
Set Fir post, for ¼ sec. cor., from which  
A Fir 10" dia., bears S.21°E., 20 lks. dist.  
A Fir 12" dia., bears N.30°W., 26 lks. dist.

G.G. Stewart, Wit: H.F. Roeder; N.E. Richardson; Frank Garnel; Otto Moore - Nov. 14, 1921 - Vol. 3 Page 100; C.S. File 2/23 Field Book 35 Page 44

-----  
Decayed stake and one BT found.  
Put 1" x 4" round eye bar for corner.  
New BTs - 24 Fir S.43°W., 35 lks.  
18" Fir (orig) N.45°E., 57 lks.

BLM resurvey by Jelley, under Group #563, Survey in 1964 (DCSO records, Volume 33 Page 13749)

-----  
The ¼ sec. cor., perpetuated and recorded by G.G. Stewart, in 1921, from the orig. cor. stake and one bearing tree, which are no longer in existence, monumented with an eye bolt, 1" bearing tree mkd. by Stewart:

A sawed Fir stump rotted and burned 24" dia., bears S.43°W., 36 lks. dist., no marks remaining.

At the corner point

Set a Iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd: T 25 S R 7 W

¼  
S 30 | S 29  
1964

from which new bearing trees

A Fir 11" dia., bears S.74°E., 12½ lks., mkd. ¼ S29 BT.

A Fir 5" dia., bears S.81°W., 25 lks., mkd. X BT.

Reset eye bolt alongside the iron post.

Fd. OK, H. Northcraft, 1986, M 102-79

Fd. OK, Karl Ferrier, December 1989, M 109-54 A&B

Fd. OK, Robert Dolan, December 1990, M 111-28

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/8/2000 - C.S. File 66/14-40

-----  
Found - 1964 BLM BC/IP, protrudes 3" above ground. 1964  
Eye bolt from 1921 along north edge of 1964 BC/IP.  
18" now rotted remains of a D.Fir stump bears  
S.43°W., 23.8 ft. 1921 **continued next page**

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

5" now 10" dia., D.Fir with a fully healed single blaze, bears S.81°W., 16.5 ft. 1964  
11" now 19" dia., D.Fir with a healed blaze, bears S.74°E., 7.4 ft. (Rec. S.74°E., 8.2 ft.) 1964  
North - South fence line 2 ft. East of corner.  
New BTs- 9" G.Fir double blazed & scribed "¼ S30 CS BT" bears S.33°W., 30.5 ft.  
5" R.Cedar double blazed & scribed "X CS BT" bears N.56°E., 17.8 ft.

Fd. Ok by D. Edwards, Feb. 2006 - M149-71  
Fd. Ok by D. Edwards, March 2010 - 2010-0032 A&B  
Fd. Ok by C. Sweeden, 11/2014 - M168-68