

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W. H. Byars, under Contract #202 dated March 11, 1874 (DCSO records, Volume 9 Page 3896)

Set Fir post cor. to secs. 17, 18, 19 and 20, from which
A Fir 10" dia., bears N.27°E., 12 lks. dist.
A Laurel 10" dia., bears S.37½°E., 10 lks. dist.
A Fir 12" dia., bears S.29½°W., 76 lks. dist.
A Fir 12" dia., bears N.26°W., 9 lk. dist.

GL0 survey by Wm. P. Heydon, under Contract #656 dated May 21, 1896 (DCSO records, Volume 9 Page 3915)

I found corner to be a Fir post, badly decayed and lying on upon the ground. I set a new Fir post, 3 ft. long, 4" sq., 24" in the ground in place of old post, from which the orig. witness bear as described by the Surveyor General, except the Laurel in section 20, of which I could find no trace. I therefore establish a new witness in its place, to wit.
A Fir 20" dia., bears S.45°E., 96 lks. dist.,
mkd. T25S R7W S20 BT.

Doug. County Surveyors Office - James W. Byron, Deputy - S. Bilow - Nov. 6, 1957 - C.S. File 49/10-2

Found - Rotted snag, orig. BT 12" now 16" Fir N.27°E., 7.9 ft. Scribe marks visible.
Find 18" Fir face rotted. No scribe marks found.
Checks brg. & dist. for NW orig. BT.
The SE orig. BT gone.
I open orig. 12" now 16" Fir S.29½°W., rec. 50.2 ft.
I find dist. should be 31.4 ft. (checks brg)
Find scribing "T".
Set Brass cap at cor. mkd. S18|S17 T25S R7W County Surveyor's
S19|S20 Office, 1957
New BTs - 16" R.Fir N.28°W., 6.0 ft. scribed S18 T25S R7W CSBT
30" R.Fir S.22°E., 25.0 ft scribed S20 T25S R7W CSBT
I rescribe the orig. SW BT. 16" R.Fir S.25°W., 31.4 ft. scribed S19 T25S R7W CS BT.
6" R.Fir, East 57.0 ft. scribed S17 T25S R7W CS BT.

(Cont. Next Page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Jelley, under Group #563, Survey 1964
(DCSO records, Volume 33 Pages 13753-54)

The sec. cor., recorded and remonumented by James Byron, in 1957, with an iron pipe, 1" dia., protruding 12" above the ground, firmly set, with brass cap, from which the remaining original bearing trees

A Fir snag 13" dia., bears N.27°E., 12 lks. dist. with fragmentary scribe marks visible on opened blaze.

A Fir 15" dia., bears S.26½°W., 47½ lks. dist., with scribe marks BT visible on opened blaze. Remarkd by Byron, S19 T25S R7W CS BT. (Rec.S.29½°W., 76 lks.)

A Fir 22" dia., bears N.26°W., 9 lks. dist., with rotted blaze, no orig. marks visible. Remarkd by Byron with fragmentary scribe marks visible on partially healed blaze.

and bearing trees marked by Byron

A Fir 8" dia., bears East, 87 lks. dist., with a healed double blaze.

A Fir 35" dia., bears S.22°E., 38 lks. dist., with scribe marks T25S CS S20 BT visible on a partially healed blaze.

and a new bearing tree

A Fir 28" dia., bears N.45°E., 57 lks. dist., mkd. T25S R7W S17 BT.

Add marks BLM 1964 to bottom of brass cap.