

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Wm. P. Heydon, under Contract #656 dated May 21, 1896 (DCSO records, Volume 9 Page 3908)

Set a Fir post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4S on N. face, from which

A Fir 6" dia., bears N.45°W., 40 lks. dist. mkd.

1/4 S BT.

A Fir 12" dia., bears N.45°W., 40 lks. dist., mkd.

1/4 S BT.

Claude Kerr, November 1953, C.S. File 41/228

Found - One orig. BT, now a 30" stump. Chopped into old face and found the markings.

I set the corner from this original BT.

Set a stake with a 1/2" x 1/2" x 18" steel rod alongside, from which:

New BTs - 13" W.Fir bears N.20°E., 4.3 ft. scribed 1/4 S9 BT.

13" W.Fir bears S.33°W., 2.6 ft. scribed 1/4 S16 BT.

Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; S.A. Bilow - April 13, 1959 - C.S. File 49/76-2

Found - Orig. BT, now 14" W.Fir scribed by Kerr, 1953, 4.3 ft., I do not find his SW BT nor rod set for corner.

30" stump scribed "BT", this is BT used by Kerr to set corner.

Now 24" W.Fir snag, previously opened, shows good scribing "BT". This is also an orig. BT., N.45°W., 26.4 ft. I use this BT to set corner which checks record dist. to stump, but I find bearing should be S.25 1/2°W., record S.13°E.)

BTs face to this corner rather than to Kerr's corner.

Kerr's corner bears N.85°W., 14.5 ft.

Set Brass cap at cor. mkd. County Surveyor's Office, 1959

1/4 S 9

S16 T25S R7W

New BTs - 13" Chinguapin bears N.43 1/2°W., 55.8 ft. scribed 1/4 S9 CS BT.

12" W.Fir bears S.83°E., 44.7 ft. scribed 1/4 S16 CS BT.

Note: Corner is in South edge of logging road.

(Cont. Next Page)

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note: I destroy scribing on Kerr's NE BT.

Found OK, March 1967 - V.R.T. (DCSO office) C.S. 54/10-9A

BLM resurvey by McMullen in 1985, found 1959 DCSO brass cap and 3 BTs. (DCSO record, Volume 47 Page 18170)

Doug. County Surveyors Office - Randall Smith; Stephen Flause
Dec. 4, 1989 - C.S. File 64/3-11

Found - 1959 DCSO brass cap on an I.P. flush with ground.
12" now 20" dia. 2½ ft. high rotted D.Fir stump,
with scribing "BT" found on a previously
opened blaze., bears S.25½°W., 23.4 ft (agrees
with most recent renewals) Orig. BT.
13" now 10" dia., broken & rotted Chinquapin stump,
no scribing or blazes visible, bears N.43½°W.,
55.8 ft. (agrees w/record.)
12" now 31" dia. D.Fir with a fully healed single
blaze bears S.83°E., 45.5 ft.
13" now 29" dia., D.Fir previously opened on south
side & scribing axed out. This BT went to an
erroneous corner set by Kerr in 1953 No blazes
found facing 1959 DCSO corner. Tree bears
N.64½°W., 13.9 ft. which agrees with 1985 BLM
survey record.

New BTs - 31" dia. D.Fir double blazed & scribed "1/4 S9 CS
BT" bears N.64½°W., 13.9 ft.
10" dia. D.Fir double blazed & scribed "1/4 S16 CS
BT" bears S.24½°W., 14.5 ft.
7" dia., D.Fir double blazed & scribed "1/4 S9 CS
BT" bears N.74°E., 13.9 ft.

Corner lies at edge of old logging road, approx. 80 ft. south
of a gravel road.