

PRIMARY CORNER DESCRIPTION Special M.C. Section 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management survey by Rick McMullen under Group #1246, Survey, 1985 (DCSO records, Volume 47 Page 18174)

Intersect the adjusted record meanders on the left bank of the Umpqua River, point for the special meander cor. on the N. and S. center line of section 9.
Set a Iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd: SMC

C
S | 9
C
1985

from which

A Fir 11" dia., bears S.29½°E., 27 lks. dist.,
mkd. S 9 SMC BT.

A Cedar 10" dia., bears S.57°W., 13½ lks. dist.,
mkd. S 9 SMC BT.

Deposit a white "DEEP-1" marker at base of iron post.

Doug. County Surveyors Office - Randall Smith; Stephen Flauser
Dec. 1, 1989 - C.S. File 64/3-9

(CORNER REPORT ONLY, NO NEW ACCESSORIES)

Found - 1985 ¾" BLM brass cap on a 2½" O.D. iron pipe protrudes 2" above ground.

11" now 11" dia., D.Fir with a partially healed single blaze, scribing visible "S9 SMC BT" bears S.29½°E., 17.8 ft.

10" now 10" dia. Cedar with a partially healed single blaze scribing visible "S9 SMC BT" bears S.57°W., 9.3 ft. (Rec. S.57°W., 8.9 ft. dist. is a face measurement)