

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Dennis Hathorn, Deputy, Contract #63 dated March 22, 1856 (DCSO records, Vol. 9 Page 3867)

Set 1/4 section post, from which
 A B.Oak 18" dia., bears N.89°W., 693 lks.
 A B.Oak 15" dia., bears South, 367 lks.

BLM resurvey by Lynn Roseberry, under Group #645, survey, July 1967/Sept. 1968 (DCSO records, Vol. 36 Pg. 14959)

The 1/4 sec. cor., determined at record bearing and distance from the remaining original bearing tree:

 A B.Oak 40" dia., bears N.89°W., 693 lks. dist., with scribe marks 1/4 visible on opened blaze.

At the corner point

Set a Iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd: T 25 S R 7 W

1/4 S 27
 S 28

from which new bearing trees

 A Cedar 7" dia., bears N.7 1/4°E., 80 lks. dist., mkd. 1/4 S27 BT.

 A Cedar 8" dia., bears S.16°W., 100 lks. dist., mkd. 1/4 S34 BT.

Douglas Co. Surveyors Office - Randall Smith, Stephen Flauser; Sept. 17, 1996 - C.S. File 65/9-16

Found - 3 1/4" dia. brass cap on a 2 1/2" O.D. iron pipe, protrudes 7" above ground (1968)

Accessories Found -

 18" now 41" dia. down B.Oak, (fallen on face) root hole bears N.89°W., 457.4 ft. (agrees with rec.) O.B.T.

 7" now 21" dia. Cedar, with a fully healed single blaze, bears N.7 1/4°E., 52.8 ft. (agrees with rec.) 1968

 8" now 25" dia. Cedar, with a fully healed single blaze, bears S.16°W., 66.0 ft. (agrees with rec.) 1968

New Accessories -

 27" dia. D.Fir, double blazed and scribed "1/4 S27 CS BT" bears N.87°W., 328.4 ft.

 26" dia. Cedar, double blazed and scribed "1/4 S34 CS BT" bears S.72°E., 19.8 ft.