

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, Deputy, Contract #63 dated
March 22, 1856 (DCSO records, Vol. 9 Page 3868)

Set ¼ sec. post, from which
 A Fir 30" dia., bears N.45°W., 12 lks.
 A Fir 36" dia., bears S.50°W., 36 lks.

Doug. County Surveyors Office - Milo Godfrey, Deputy - Mike
Stone - December 26, 1962 O C.S. File 49/76-23

Found - Rotten Fir stump, broken off too low to find scars
 or scribing.
 36" Fir snag N.45°W., 7.9 ft., shows good scar,
 impossible to open, log lies almost against
 face, still alive but broken off.
 Fir tree, S.50°W., 24.8 ft. uprooted & down, not
 recent, has slid about 20 ft. downhill, bark
 scribing visible on under side.

Set Witness Corner 5 ft. East of ¼ corner, with brass cap mkd:
County Surveyor's Office WC ¼ S 22 5' W. to cor.
 S 27 T25 S R7W

New BTs - 32" D.Fir N.21°W., 20.3 ft. mkd. WC ¼ S22 CS BT.
 6" W.Fir S.12°E., 27.6 ft. mkd. WC ¼ S27 CS BT.
Corner lies on precipitous North slope, approx. 300 ft.
South of river.

Fd. Ok by David Edwards, July 2001 - M 138-39