

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 3/10/1998 - C.S. File 66/2-3

Found - 2½" dia., brass cap on a 1½" O.D. iron pipe, protrudes 12" above ground. 1962
36" now 30" dia., 2½ ft. high rotted D.Fir stump, no scribing or blazes visible, bears S.80°E., 30.0 ft. to center (Rec. S.80°E., 27.7 ft. possible face measurements) 0BT
5" now 22" dia., D.Fir with a fully healed double blaze, bears S.74°W., 9.0 ft. (Agrees with rec.) 1962
10" now 27" dia., D.Fir with a fully healed double blaze, bears S.60°E., 42.5 ft. (Agrees with rec.) 1962
New BTs - 15" dia., Madrone, bark scribed "¼ S14 CS BT" bears N.27°W., 52.4 ft.
8" dia., D.Fir, double blazed and scribed ¼ CS BT" bears N.20°E., 30.1 ft.
Note - See sketch in file.

Fd. & used on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1905, surveyed April/May 1999. (DCSO rec. Vol. 53 page(s) 20617-8)