

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & S 18 of T25-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, Contract #272 dated August, 1877
(DCSO records, Volume 9 Page 3848)

Set a Fir post, 4" dia. 40" long, 1/3 in the ground, from
which

A Fir 30" dia. bears N.82°E., 64 lks. dist.

A Fir 30" dia. bears N.2°W., 150 lks. dist.

Wm. P. Heyden, Contract #656 dated May, 1896 (DCSO records,
Volume 9 Page 3853) (duplicate information on Page 3919)
1/4 sec. cor. gone. Witness trees still standing but markings
overgrown.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy; Mike
Stone - July/Aug. 1963 - C.S. File 49/123-95

Found - 37" Fir N.2°W., 99.0 ft. Faint bark scribing visible
"¼". Tree alive & standing, top partly dead.

36" Fir N.82°E., 42.2 ft. tree recently uprooted and
down. Bark shows evidence of having been face
off with axe. No scribing.

Set brass cap at cor. mkd: County Surveyor's Office, 1963
T25S R7W ¼ S13|S18 R6W

Build mound of stone around cap.

New BTs - 22" D.Fir N.1°E., 8.2 ft. mkd: ¼ S18 CS BT.

15" D.Fir S.85°W., 20.4 ft. mkd: ¼ S13 CS BT.

Corner lies on steep rocky SE slope, approx. 100 ft. south of
top of spur & between two large outcrops of rock.

Bureau of Land Management - Lynn Roseberry, Group #645. Survey
commenced July 20, 1967, Completed Sept. 25, 1968. (DCSO
records, Volume 36 Page 14947)

Found - 1963 County brass cap.

A root hole, bears N.82°E., 64 lks. dist. with an
uprooted Fir, 36" dia. alongside with axe marks
visible. (orig.)

A Fir 37" dia. bears N.2°W., 150 lks. dist. with
scribe marks ¼ visible on bark. (orig.)

A Fir 23" dia. bears N.1°E., 13 lks. dist. with
scribe marks ¼ S18 CS BT visible on open blaze.

A Fir 16" dia. bears S.85°W., 32 lks. dist. with
scribe marks ¼ S13 CS BT visible on open blaze.

Found OK, Feb. 1996 by K. DeGroot - M 124-3

continued next page

TOWNSHIP 25 RANGE 07 POINT IDENTIFIER # 700440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 13; & S. 18 of T25-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1905, surveyed April/May 1999. (DCS0 rec. Vol. 53 page(s) 20610-11)

The 1/4 sec. cor. of secs. 13 & 18, perpetuated by Godfrey, of the DCS0 in 1963, monumented with an iron post firmly set projecting 12" above the ground in a collar of stone, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A root hole, bears N.82°E., 42.3 ft.

A burned snag, 36" diam., bears N.2°W., 99.0 ft., with a healed blaze.

and the remains of the bearing trees mkd. by Godfrey

A burned snag, 26" diam., bears N.1°E., 8.6 ft., with a healed blaze.

A burned snag, 18" diam., bears S.85°W., 19.9 ft., with a healed blaze. (Record, 21.1 ft.)

and a new bearing tree

A fir, 18" diam., bears N.78°E., 90.7 ft., mkd. ¼ S18 BT.

No other trees within limits.

Cor. is located on a steep rocky slope. This area has been logged and burned by a hot fire.

Fd. BC & BTs 1/2025 - by N. Hibbs M185-26