

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5,1902 - (DCSO rec Vol 10 Pg 3963)

Set a Hemlock post 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S12 on the W. and S7 on the E. face, from which

- A Fir 36" dia., bears S.56°E., 30 lks. dist. mkd. ¼ S BT.
- A Fir 48" dia., bears S.45°W., 10 lks. dist. mkd. ¼ S BT.

GLO survey by Morris Wygant, compassman for Zachariah M. Derrick, U.S. Deputy Surveyor, under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3969)

The ¼ sec. cor. bet. secs. 7 and 12, which is a sandstone (instead of a Hemlock post), firmly set, mkd. ¼ on W. face, and witnessed as described by the Surveyor General, and which I now change to refer to sec. 12, T25S R9W only.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Sept/Oct. 1968 - C.S. File 54/72-43

Found - Orig. 48" Fir, now 51" sawed stump, S.45°W., 6.6 ft., we chop open and find "¼" scribe.

No trace of corner stone or other orig. BT.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 25 S	R
9 ¼ S 12		8
W	1968	W

1/2" steel pipe bears S.47°E., 2.8 ft. from BC.
New BTs- 51" Fir stump S.45°W., 6.6 ft. mkd. ¼ S12 CS BT.
42" Fir stump N.57°W., 55.6 ft. mkd. ¼ S12 CS BT.
Corner lies on steep southerly slope in large clear-cut area and 75 ft. South of Weyerhaeuser Rd. #2000.

Tony Hostetter - For: Weyerhaeuser Co. - June 9, 2015 - C.S. File 65/89-51

Found - 1968 Douglas Co. Surveyor brass cap and BTs as described C.S. File 54/72

- New BTs-
- 20" fir, BT tag, bears N.79°E., 10.8 ft to 6" spike, placed below tag.
 - 15" fir, BT tag, bears S.14°E., 14.9 ft to 6" spike, placed below tag.
 - 17" fir, BT tag, bears N.59°W., 17.8 ft to 6" spike, placed below tag.
 - 8" fir, BT tag, bears N.19°W., 1.7 ft to 6" spike, placed below tag.