

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by - A. R. and S.C. Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 9 Page(s) 3932/35) (Note: Pages 3933 and 3934 duplicates)

Cor. to secs. 5, 6, 31 and 32, on steep side hill, Set Fir post 4 ft. long, 4" dia. or sq., from which the following witness trees are

- Fir 36" dia., bears S.10°E., 33 lks. dist.
- Fir 25" dia., bears S.10°W., 40 lks. dist.
- Hemlock 10" dia., bears N.55°E., 49 lks. dist.
- Fir 6" dia., bears N.87°W., 13 lks. dist.

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4711)

The cor. to secs. 5, 6, 31 and 32, Post destroyed. Set new Cedar post, 3 ft. long, 4" sq., 24" in the ground, for cor., (determined from 2 of the orig. witness trees) mkd. T25S S32 on NE.; R8W S5 on SE.; Tp 26 S S6 on SW.; R8W S31 on NW. faces, with 1 notch on W. and 5 notches on E. edges, from which

- A Fir 36" dia., bears S.10°E., 33 lks. dist., mkd. T26S R8W S5 BT.
 - A Fir 25" dia., bears S.10°W., 40 lks. dist. mkd. T26S R8W S6 BT.
- NE. and NW. witness trees destroyed. I made new ones as follows:
- A Fir 20" dia., bears N.70°E., 65 lks. dist., mkd. T25S R8W S32 BT.
 - A Fir 60" dia., bears N.8°W., 100 lks. dist. mkd. T25S R8W S31 BT.

GLO survey by Morris Wygant, compassman for Zachariah M. Derrick, U.S. Deputy Surveyor, under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3966)

The Sec. Cor., which is a badly decayed post, mkd. and witnessed as described by the Surveyor General. I reestablish this cor. as follows: I destroy the old cor. and at the exact point, Set a Fir post 3 ft. long 4" sq., 24" in the ground mkd. T25S S32 on NE.; R8W S5 on SE.; T26S S6 on SW.; and S31 on NW. faces; with 5 notches on E. and 1 notch on W. edge; from which

- A Fir 28" dia., bears N.70°E., 65 lks. dist. mkd. T25S R8W S32 BT.

(Cont. Next Page)

TOWNSHIP 25 RANGE 08 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32; 5 & 6, T26-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A Fir 42" dia., bears S.10°E., 33 lks. dist. mkd. T26S R8W S5 BT.
A Fir 34" dia., bears S.10°W., 46 lks. dist. mkd. T26S R8W S6 BT.
A Fir 72" dia., bears N.8°W., 100 lks. dist. mkd. T25S R8W S31 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 1968 - C.S. File 54/72-39

Found - Orig. 42" now 60" Fir, alive, S.10°E., 21.8 ft.,
bark scribe visible, poor condition.
Orig. 34" now 52" Fir, alive, S.10°W., 26.4 ft.,
bark scribe visible, poor condition.
28" now 40" Fir, alive, N.70°E., 42.9 ft., no scribe
nor scar found, injured. (1896 BT)
72" now 82" Fir, alive, N.8°W., 66.0 ft. bark scribe
visible, fair condition.

Set Brass cap at cor. mkd: County Surveyors Office
T25S R8W S 31 | S 32
T26S S 6 | S 5
1968

New BTs- 11" Hemlock N.12°E., 23.8 ft. mkd. T25S R8W S32 CSBT
10" Hemlock N.12°W., 18.8 ft. mkd. T25S R8W S31 CSBT
8" Hemlock S.65°W., 18.7 ft. mkd. S6 CS BT.
13" Hemlock S.72°E., 26.1 ft. mkd. T26S R8W S5 CSBT
Corner lies on precipitous SE. slope in large old Fir and
Hemlock.

FD 1968 DCSO Brass cap as described in C.S. 54/72 - By T.
Hostetter - 2/2018 - M174-25