

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Charles L. Campbell, Deputy Surveyor, under Contract #747,, dated May 5,1902 - (DCSO records Vol. 9 Page(s) 3958)

Set a sandstone 24x15x10 ins., 18" in the ground for cor. of secs. 25, 30, 31 and 36, mkd. with 5 notches on the N. and 1 notch on the S. edges, from which

A Fir 48" dia., bears N.35°E., 79 lks. dist. mkd. T25S R8W S30 BT.

A Fir 44" dia., bears S.85°E., 25 lks. dist. mkd. T25S R8W S31 BT.

A Fir 38" dia., bears S.37¼°W., 49 lks. dist. mkd. T25S R9W S36 BT.

A Fir 40" dia., bears N.32 3/4°W., 50 lks. dist. mkd. T25S R9W S25 BT.

GLO survey by Morris Wygant, compassman for Zachariah M. Derrick, U.S. Deputy Surveyor, under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 10 Page(s) 3967)

Intersect the cor. of secs. 25, 30, 31 and 36 which is a sandstone, firmly set, mkd. and witnessed as described by the Surveyor General, and which I now change to refer to secs. 25 and 36, T25S R9W only.

BLM resurvey by James E. Jelley; Jack W. Bowder, Cadastral Surveyors, under Group #767, Surveyed April/May 1972 - (DCSO records Vol. 36 Page(s) 15032-33)

The cor. of secs. 25 and 36 only, monumented with an iron pipe 1" dia., firmly set, projecting 6" above ground, from which the remains of the original bearing trees:

A sawed Fir stump 54" dia., bears N.35°E., 79 lks. dist., no marks visible.

A sawed Fir stump 40" dia., bears S.85°E., 25 lks. dist. with fragmentary scribe marks visible on decayed blaze.

A sawed Fir stump 54" dia., bears S.37¼°W., 49 lks. dist., no marks visible on open blaze.

A sawed Fir stump 58" dia., bears N.32 3/4°W., 50 lks. dist., no marks visible, and a nail with "W" embossed on head, driven into base.

and a bearing tree of which I have no record

A sawed Fir stump 72" dia., bears N.87°E., 71 lks. dist., with a nail with "W" embossed on head, driven into base.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 25 RANGE 09 POINT IDENTIFIER # 700200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only, (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<table border="0"><tr><td>T 25 S</td><td> </td><td>T 25 S</td></tr><tr><td>S 25</td><td> </td><td>R 8 W</td></tr><tr><td>S 36</td><td> </td><td>S 31</td></tr><tr><td>R 9 W</td><td> </td><td></td></tr><tr><td colspan="3" style="text-align: center;">1972</td></tr></table> <p>Reset iron pipe alongside the iron post.</p>	T 25 S		T 25 S	S 25		R 8 W	S 36		S 31	R 9 W			1972		
T 25 S		T 25 S													
S 25		R 8 W													
S 36		S 31													
R 9 W															
1972															
<p>Henry R. Reppeto - For: Weyerhaeuser Co. - Feb. 6, 1976 - C.S. File 58/90 and M 59-34</p> <p style="text-align: center;">-----</p> <p>Found BLM monument with the following accessories: 54" D.Fir stump bears N.35°E., 79 lks. Orig. BT. 40" D.Fir stump bears S.85°E., 25 lks., Orig. BT. 54" D.Fir stump bears S.37¼°W., 49 lks., Orig. BT. 58" D.Fir stump bears N.32 3/4°W., 50 ks., Orig. BT. 72" D.Fir stump bears N.87°E., 71 lks.</p>															
<p>Tony Hostetter - For: Weyerhaeuser Co. - Feb. 2020 - C.S. File 65/106-7</p> <p style="text-align: center;">-----</p> <p>Found - 1972 BLM Brass cap 72" Fir stump, WEYCO tag, "W" nail, bears N.87°E., 46.9 ft to center (BLM record N.87°E., 46.9 ft). 4 OBTS described in BLM record Vol. 36, PG 15033, are in place, deteriorated with no tags or other markings. New BTs- 16" Fir tall stump, BT tag, bears S.89°E., 12.8 ft to 6" spike, placed below tag. 12" Fir tall stump, BT tag, bears N.16°E., 5.3 ft to 6" spike, placed below tag. 13" Fir stump, BT tag, bears S.45°W., 8.5 ft to 6" spike, placed below tag.</p>															