

PRIMARY CORNER DESCRIPTION Cor. Secs. 21, 22, 27, & 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Otto L. Draper, US Transitman, under Special Instructions dated Dec. 24, 1920 - (DCSO records Vol. 22 Page(s) 9580)

-----  
Set an iron post, 3 ft. long, 2" dia., 27" in the ground, for cor. of secs. 21, 22, 27, & 28, with brass cap mkd

T26S R1E  
S 21|S 22  
S 28|S 27  
1928

from which

- A chinquapin, 8" dia., bears N.59°E., 19 lks., mkd: T26S R1E S22 BT.
- A fir, 4" dia., bears S.56°E., 25 lks., mkd: T26S R1E S27 BT.
- A madrone, 6" dia., bears S.44°W., 10 lks., mkd: T26S R1E S28 BT.
- A fir, 4" dia., bears N.30°W., 10 lks., mkd: T26S R1E S21 BT.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - Karen Cheney - Mike Tompkins - Dec. 20, 1976 - C.S. File 62/9-10

-----  
Corner referenced out for road construction.  
Found - 1928 GLO brass cap extending 14" above ground and firmly set. Properly mkd. cap from which  
Orig. 8", now 12" Chinquapin, N.62½°E., 13.2. ft. (rec. N.59°E. 12.5 ft.) Alive with rotting face partially visible. No scribing visible.  
Orig. 4" now 8" D.Fir S. 58½°E., 15.6 ft. (rec. S.56°E., 16.5 ft.) Alive and well healed.  
Orig. 6" now 6" Madrone S.31°W., 6.6 ft. (rec. S.44°W., 6.6 ft.) Alive with no blazes or markings visible.  
Orig. 4" now 8" D.Fir N.22°W., 7.3 ft. (rec. N.30°W., 6.6 ft.) Alive and well healed.

Due to impending road construction, we reference this corner as follows:

- Set - Boat-spike in base of 24" D.Fir N.44°W., 47.9 ft.
- Boat-spike in base of 34" I.Cedar S.50°W., 42.7 ft.
- We leave brass cap in place/

-----  
Note dated 6/16/1983 - Corner visited by County. Ok - not disturbed by construction VL

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - S. Flause & R. Smith - 3/11/88  
CS. 62/50-11

-----

Found - 1928 GLO brass cap properly mkd. on a 2" dia. I.P. loosely set and leaning easterly protrudes approx. 14" above ground.

(Measurements as follow are taken to what would be a plumb position of cap):

8" chinquapin now a 12" DBH chinquapin with a rotting partially healed single blaze, no scribing visible, bears N.62½°E., 13.2 ft (agrees with 1976 Renewal. Orig. rec. N.59°E., 12.5 ft.)

4" Fir, now a 9" DBH D.Fir with a well healed double blaze, bears S.58½°E., 15.6 ft. (agrees with 1976 Ren., orig. record S.56°E., 16.5 ft.)

6" Madrone now a 6" DBH Madrone with a possible partially healed double blaze with no scribing visible bears S.31°W., 6.6 ft. (agrees with 1976 record, orig. record S.44°W., 6.6 ft.)

4" Fir now a 9" DBH D.Fir with a fully healed double blaze, no scribing visible bears N.22°W., 6.6 ft. (Bearing agrees with rec. in 1976 renewal and dist. agrees with orig. rec.)

A boat spike in base of a 24" D.Fir now a 37" DBH D.Fir bears N.44°W., 47.9 ft. 1976

A Boat spike in the base of a 34" Incense Cedar now a 42" DBH Incense Cedar bears S.49°W., 43.5 ft. (Rec. S.50°W., 42.7 ft.)

Set - Bearings and distances agree well with record when measured from plumb position of found monument. Monument is therefore straightened up to restore to a plumb position and a 2 ft. dia. 1 ft. tall mound of stone is built around the protruding monument.

Road construction did not disturb monument location. Mon. is approx 35' north westerly from a logging unit access rd. & near the top of a moderate northwesterly slope.