

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 cor. for Sec. 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4101)

A Fir 48" dia., for 1/4 sec. cor. on S. bdy. of sec. 32, I mark 1/4 S32 on N. side, from which
 A Hemlock 9" dia., bears N.61°E., 15 lks. dist. mkd. 1/4 S32 BT.
 A Hemlock 10" dia., bears N.9°W., 12 lks. dist. mkd. 1/4 S32 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Dec. 4, 1969 - C.S. File 54/94-73

Found - 48" D.Fir Corner tree, now snag, rotted face, scribe visible "1/4 S32".
 No trace of small bearing trees.
This corner lies at top of 60 ft. bluff, BTs probably went over.
Set brass cap on N. side of Cor. Tree, directly under face, cap mkd. County Surveyors Office
 T26S R1W 1/4 S 32
 T27S 1969
New BTs- 7" Cedar N.89°W., 20.0 ft. mkd. "1/4 S32 CS BT"
 8" Cedar N.50°W., 20.0 ft. mkd. "1/4 S32 CS BT"