

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4113-14)

-----  
At a point 22.35 chs. E. of the ¼ sec. cor. on S. bdy. of sec. 35, T25S R1W, I establish ¼ sec. cor. on N. bdy. of sec. 1 as follows:

Point for ¼ sec. cor. on N. bdy. sec. 1 falls on a conglomerate rock in plate, 3x2x2 ft. above ground on which I cut a cross (X) at exact cor. point, "¼ S" of cross, from which

A Fir 24" dia., bears S.50°E., 39 lks. dist. mkd. ¼ S1 BT.

A Cedar 20" dia., bears S.11°W., 45 lks. dist. mkd. ¼ S1 BT.

-----  
Dennis Gaylord, U.S. Forest Service (Deputized by the County) Sept. 15, 1977 - C.S. File 59/40-12

-----  
Found - A 26" broken Fir stob bears S.50°E., 25.74 ft. Has a healed scar. Open and find scribing and reverse "S1BT"

A 33" Cedar, orig. 20", bears S.11°W., 29.7 ft. Has a healed scar. Cedar is alive and well.

Placed County BT sign on both tree and stob.

No monument found. Apparently the corner stone has broken and rolled down hill.

Set 2½" brass cap on a 1" I.P. set by reference to orig. BTs Set in a mound of stone 4 ft. wide at base by 4 ft. high on downhill side. Brass cap stamped "County Surveyors Office T26S R1W ¼ only S1 1977"

New BT - A 13" D.Fir bears S.42°E., 88.7 ft. scribed "¼ S1 CS BT" on a double blaze. Placed DCSO BT sign in Fir.

Found two Fir trees 100 ft. ± East which appeared to be bearing trees but when chopped out, no scribing was found. Face well chopped by an axe, 50 years growth over face.