

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 700246

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 30 only, T26-1E

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Otto L. Draper, U.S. Transitman, under Special Instructions, dated Dec. 24, 1920 - (DCSO records Vol. 22 Page(s) 9523)

Point for the ¼ sec. cor. of sec. 30 only, later determined. Set an iron post 3 ft. long, 1" dia., 27" in the ground for the ¼ sec. cor. of sec. 30 only, with brass cap marked:

 | ¼ S 30
 1928

from which

- A Fir 20" dia., bears N.31°E., 62 lks. dist. mkd. ¼ S30 BT
- A Fir 20" dia., bears S.20°E., 29 lks. dist. mkd. ¼ S30 BT

Survey by Burton W. Holt - For: Sun Studs - March 28, 1980 - C.S. File 58/176-26

Found - Both BTs with good healed over scars and Forest Service BT tags. Both trees in excellent condition and both are now an approx. 32" in dia. Orig. hole where the corner pipe had been, and was able to identify by the calls from the two BTs. The area had been logged over in a selective-cut hi-lead logging show. The brass cap and pipe were pulled and lost during the logging.

Set a 5/8" x 30" iron rod, in the orig. hole, with an alum. cap mkd. T26S R1E ¼ 30 418.
Did not mark any new trees.