

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1, T26-1

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4077)

 Set a basalt stone 18x12x6 ins., 12" in the ground for closing cor. of T26S Rs 1 E. and 1 W. marked CC on S. with 6 grooves on S., E., and W. faces, from which
 A Fir 6" dia., bears S.43½°E., 96 lks. dist. mkd. T26S R1E S6 BT.
 A Fir 36" dia., bears S.31°W., 73 lks. dist. mkd. T26S R1W S1 BT.

GLO resurvey by Otto L. Draper, U.S. Transitman, under special instructions dated Dec. 24, 1920 - (DCSO records Vol. 22 Page(s) 9532)

 Intersect the old closing Tp. cor. of Tps. 26 S., Rs 1 W and 1 E., which is a basalt stone, 12x6x6 ins. above ground, marked CC on S., with 6 notches on E., E., and W. edges. Alongside of old cor. stone, Set an iron post 3 ft. long, 3" dia., 27" in ground, for closing cor. of Tps. 25½ and 26 S., Rs. 1 E. and 1 W., with brass cap marked:

T25SR1W	
S 36	
T26S	T25½S
R1W	R1E
S1	S31
C C	
1928	

from which
 A Fir stump 6" dia., bears S.43½°E., 96 lks. mkd. T26S R1E S6 BT. (destroy marks)
 A Fir 36" dia., bears S.31°W., 73 lks. dist. mkd. T26S R1W CC BT. (old BT)
 A Fir 18" dia., bears S.38°E., 109 lks. dist. mkd. T25½S R1E S31 CC BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct. 17, 1966 - C.S. File 52/30-28

 Found - 2" I.P. and 1928 GLO brass cap attached, properly marked.
 18" now 26" Fir, S.38°E., 71.9 ft., shows very good scar, alive, we do not open.
 Orig. 36" now 48" Fir, now badly rotted stump, S.31°W., 48.2 ft., shows fragmentary scribe marks "T2" on shattered blaze.

(Cont. Next Page)

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE Cor. for Sec. 1, T26-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New BT - 15" Pine S.64°W., 23.6 ft. mkd. T26S R1W S1 CC CS BT
Corner lies on steep S. slope, approx. 140 ft. E. of shallow
ravine, course SE.

Glenn Baughman - For: U.S. Forest Service - Sept. 1980 - C.S.
File 58/229-37

Found - 1928 GLO brass cap on 3" I.P. firmly set 10" above
the ground.

A 48" Fir stump, badly rotted with scribe marks "T2"
visible bears S.31°W., 48.2 ft.

A 30" D.Fir with healed blaze, bears S.36°E., 72.6
ft. (Rec. S.38°E., 71.9 ft.)

A 16" Pine snag, with scribe marks visible on a
partially healed blaze, bears S.64°W., 23.6 ft.

New BT - A 20" D.Fir bears S.16°W., 17.8 ft. marked "T26S R1W
S1 CC BT" on a double blaze with a brass washer
stamped "LS 536" nailed into lower blaze.

James M. Stanley, ODOT - Sept/Nov. 2007 - St. Hwy 138-011V&X

Fd. 3½" brass cap stamped "US GENERAL LAND OFFICE 1928 \$250
penalty for removal T25S R1W S36

T26S R1W S1 T25½S

R1E S31"

(10-30-07)

N. 621623.895

E. 4322129.455