

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCS0 records Vol. 10 Page(s) 4243)

Set cedar post, 3 ft. long, 5 sq., 24" in the ground for ¼ sec. cor. mkd ¼ S29 on N & 32 on S face, from which
 A chinquapin, 8" dia., bears N.5°W., 14 lks. mkd: ¼ S29 BT
 A chinquapin, 8" dia. bears S.20°W., 20 lks. mkd: ¼ S32 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - June 30, 1967 - C.S. File 54/40-10

Reported as not found.
Apparently destroyed by logging.

David Edwards - For: Seneca Jones Timber - 5/2010 - M 160-76

Set - 5/8"x30" steel rebar with 2½" dia., alum. cap mkd: "LS 2339" and "2010 and as per the 1973 BLM manual set at proportionate position.
 An 18" dia., Fir bears N.7°E., 15.65 ft.
 An 11" dia., Fir bears N.41°E., 22.35 ft.
 A 7" dia., Fir bears S.76°E., 20.90 ft.
 A 6 ft. steel post is set 2' East.

Douglas Co. Surveyors Office - Crew: Stephen Flauser & Jeff Lorsung- 5/19/2021 (Filed 11/22/2021) - C.S. File 67/51-7

Found - 5/8" Iron rod with 2½" alum. cap projecting 6", (properly marked)
 24" W.Fir N.1°E., 15.65 ft. (Rec. N.7°E.) Visible scribes now fire killed. 2010
 14" D.Fir N.36°E., 22.35 ft. (rec. N.41°E.) visible scribes on partially healed single blaze.
 4"± 3 ft. burnt stub S.81°E., 20.90 (rec. S.76°E.)
 6' steel post 2.0 ft. East
New - 21"x1 ft D.Fir stump S.49°E., 19.0 ft. to 4" MAG NAIL in top center.
 24"x1 ft D.Fir stump S.61°W., 14.9 ft. to a 4" MAG NAIL in top center.
Note - Corner is on north edge of large clear-cut older repod to north mostly burnt.
 Corner is 110 ft. west of access Rd.
 Compass decl. 14½°E.
Lat: 43°16'17.87"N Long: 122°57'39.06"W