

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4211)

Set post, 3" sq. 3 ft. long 24" in the ground for 1/4 sec. cor. mkd 1/4 S on W face, from which
A fir, 20" dia., bears N.32°E., 27 lks., mkd: 1/4 S BT.
A hemlock, 18" dia., bears S.36°W., 31 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12737-8)

Point for the 1/4 sec. cor. of sec. 17, at midpoint on the E bdy of sec. 17. Set an iron post, 28" long, 2 1/2" dia., 26" in the ground with brass cap marked:
T 26 S
R 2 W
S 17
1959
from which
A fir, 24" dia., bears S.38°W., 53 lks., mkd: 1/4 S17 BT.
A cedar, 28" dia., bears N.18°W., 48 lks., mkd: 1/4 S17 BT.

Fd. Ok by R. Brown, 3/1994 - M118-53

David Edwards - For: Seneca Jones Tmbr - 1/2000 - M 134-15

Found BC & 2 BTs:
30" dia., fir S.38°W., 34.98'
37" dia. cedar N.18°W., 31.68'
Per Narrative: The 1959 BLM resurvey set the 1/4 cor. And north 1/16 cor. On the west line of section 16 and called them for section 17 only. That same survey set the 1/4 cor. on the east line of sec 16 and called it for section 15 only. Analysis of the history of Sec 16, as well as an inquiry to the state office of the BLM, indicates that these corners should be common with section 16. Therefore I utilize said corners in computing the subdivision of section 16, as shown hereon.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 2-3-2023 - C.S. File 67/55-45

Found - 3 1/4" BLM brass cap up 6"
Burned-dead 40" D.Fir S.34°W., 35.5 ft (rec. 53 lks) add 3 1/2" mag nail right side center.
Burned-dead 34" R.Cedar N.18°W., 31.8 ft. (rec. 48 lks) add 3 1/2" mag nail right side center. Cont.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

<p>Steel Lath 1 ft east. New - Burned, sawn 28"x3' hemlock stump N.27°E., 24.8 ft. 3½" mag nail top center. Burned, sawn 24"x1½" D.Fir stump, N.80°E., 32.0 ft. 3½" mag nail top center. Note - Area burnt 9/2020 Compass decl. 14½°E. Lat: 43°18'21.78"N Long: 122°57'07.03"W.</p>
