

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Corner Secs 27 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22928)

The ¼ sec. cor. of secs. 27 and 34, perpetuated by the Douglas County Surveyor's Office in 1967, monumented with an iron post, 1" dia., firmly set, projecting 5" above a collar of stone, with brass cap (properly) mkd.

from which the remains of BTs mkd by Mensch

A sawed, decayed, hemlock stump, 16" dia., bears S.10°E., 4.6 ft., with a healed double blaze.

A roothole bears N.17°W., 10.6 ft., with a fallen, decayed, hemlock snag, size indeterminate, lying alongside, with no marks visible.

and the remains of BT mkd by the Douglas Co Surveyor's Office

A sawed, decayed, hemlock stump, size indeterminate, bears N.51½°E., 15.3 ft., with fallen, decayed hemlock trunk segment lying alongside, size indeterminate, with scribe marks ¼ S27 CS BT visible on a partially healed blaze.

and new bearing trees

A fir, 10" dia., bears N.13½°E., 23.2 ft., mkd. ¼ S27 BT.

A cedar, 5" dia., bears S.53°E., 17.1 ft., mkd. ¼ S34 BT.

Corner is located 25 ft. N. of a gravel road, 12 ft. wide, bears N.70°W. and S.85°E., in a curve.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 1/31/2022 (Filed 4/13/2022) - C.S. File 67/52-12

Found - 2½" GLO brass cap (properly mkd) re-plumbed, projecting 9" in a rough stone mound.

Burnt 14" D.Fir N.13½°E., 23.2 ft.

New - ⅝"x30" I.Rod with yellow DCSO plastic cap S.53°E., 29.5 ft. in North road shoulder.

⅝"x30" I.Rod with yellow DCSO plastic cap N.84½°W., 42.2 ft in north road shoulder.

Note - Corner is 25' north of gravel road 12' wide bears N.70°W., and S.85°E., in curve.

Compass decl. 14½°E.

Lat: 43°16'17.33" N Long: 122°55'16.56" W