

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 460500

PRIMARY CORNER DESCRIPTION E 1/16 Secs. 10 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12732)

-----  
Point for the E 1/16 sec. cor. of secs. 10 & 15  
Set an iron post, 28" long, 2½" dia., 4" below the surface of the E edge of a gravel access road, 20 lks., wide, bears NW & S curving to SE, with brass cap marked:

E 1/16  $\frac{S}{S}$   $\frac{10}{15}$

1959

from which

A fir, 9" dia., bears N.42½°E., 75 lks. mkd: E 1/16 S10 BT

A fir, 10" dia. bears S.41¼°E., 78 lks. mkd: E 1/16 S15 BT

Douglas Co. Surveyors Office - Stephen J Flause, Party Chief  
- Randal W. Smith, Note keeper - 10/11/1985 - C.S. 62/29-6

-----  
Found - 1959 BLM brass cap properly marked, firmly set 7" below graveled road surface near east edge of traveled way.

Orig. 9" Fir, now a 16" dia. 6" tall fir stump with evidence of a low blaze which is opened to reveal a face and a scribed " " bears N.37°E., 49.2 ft. (Rec. N.42½°E., 49.5 ft.) (Difference in bearings apparent blunder of original survey).

An orig 10" Fir, now 15" DBH D.Fir with fully healed single blaze bears S.41¼°E., 51.5 ft. as per rec.

Set - Monument appears undisturbed despite slight distance error and apparent bearing blunder to original NE BT. Position of monument is accepted as found.

New BTs- A BT tag and boat spike are set at the new record bearing & distance in the NE BT stump.

An 8" DBH D.Fir, scribed E 1/16 S10 CS BT on a double blaze bears N.49½°W., 81.9 ft.

A 7" DBH Incense cedar, scribed E 1/16 S15 CS BT on a double blaze, bears S.29°W., 27.2 ft.

Note: From Diamond Lake Hwy (State Hwy #138) proceed NW on USFS Rd. #2-2-14, 1+ miles to Jct with USFS Rd #26-2-15. Proceed northerly along this road .5 miles to monument near private driveway & house.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2923, surveyed July 2018/March 2020- (DCSO records Vol. 59 Pages 24058)

-----  
The E 1/16 sec. cor. of secs. 10 and 15, reported by Zirpel, Jr., and Glenn in 1959; perpetuated by Monrean, in 1985; monumented with an iron post, 2½" dia., firmly set, CONT

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 460500

PRIMARY CORNER DESCRIPTION E 1/16 Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

with top 8" below the surface of a graveled road, with a brass cap (properly) mkd. from which the remains of the bearing tree reported by Zirpel, Jr., and Glenn  
A fir stump, 19" dia., bears S.41¼°E., 51.5 ft., with a healed blaze.  
and the bearing trees mkd. by Monrean  
A cedar, 21" dia., bears S.29¼°W., 27.0 ft., with a healed blaze.  
A fir, 12" dia., bears N.49¼°W., 81.7 ft., with a healed blaze.  
and a new reference monument  
An iron rod, 30" long, 5/8" dia., driven 27" in the ground, for a reference monument, bears S.24°00'45"E., 67.50 ft., with aluminum cap mkd. RM E1/16 67.5 FT TO COR S15 2018 and an arrow pointing to the cor.  
Corner is located W., 5 ft., of the center line of a graveled road, 16 ft. wide, bears S.10°E. and N.30°W.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 2/23/2022 (Filed 4/18/2022) - C.S. File 67/52-23  
-----

Found - BLM brass cap buried 4" in E Edge of gravel access rd  
A 15" burnt D.Fir stump S.41¼°E., 51.5' healed scar.  
An 8" D.Fir N.49½°W., 81.9 ft. double scar.  
A 7" cedar S.29°W., 27.2 ft. double blaze.  
Re-tag all trees.  
Note - Area burnt 9/2020  
Compass decl. 14½°E.  
Cannot disturb ground in Archaeological site. Will revisit when monument can be uncovered.  
Corner in roadway - no GPS